

May 15, 2018  
BBA Project No. 16244

Mr. Robert Stevens, P.E.  
Plant Manager  
Coletto Creek Power, LP  
P.O. Box 8  
Fannin, TX 77960

**RE: Coletto Creek Power – December 2017 Primary Ash Pond (CCR Unit No. 141) Dike Inspection**

Dear Mr. Stevens:

Bullock, Bennett, and Associates, LLC (BBA) performed a visual inspection of the Coletto Creek Primary Ash Pond dike system on December 20, 2017. The report for the 2017 inspection of the Primary Ash Pond is attached. Items requiring maintenance and observation are noted and summarized below.

- Maintain low Primary Ash Pond impoundment water levels to reduce or eliminate seepage at the toe of dike in the area of Station 84+00 to 90+00. Continue to monitor this historic seep area and repair erosional features as needed.
- Monitor the erosion observed at low elevations along the north dike interior and, if low impoundment water elevations are to be maintained on a long-term basis, consider extending the riprap to an elevation of approximately three feet below operating water surface levels.
- Pipe penetrations were observed in the dikes within the upper approximate 2 to 3 feet of the dike crest. No substantial dike erosion or indications of settlement were observed in these areas. However; one six-inch diameter steel pipe (near Sta 70+00) observed along the exterior dike slope appeared crushed and inoperable. Coletto Creek Power should review all pipes that penetrate the levee and consider proper removal of any pipes that may be identified as no longer planned for use. Additionally, given the pipes appear old, BBA recommends inspection of pipe sections that penetrate the dike and will not be removed and that are accessible for inspection via use of a remote camera system.
- Continue to mow the exterior dikes on a regular basis to improve ability to visually inspect the dike, encourage good vegetation, and maintain removal of trees and shrubs.
- Continue hog and rodent control measures. Repair areas of damaged vegetation as shown in photo 9551 and observed in localized surrounding areas.
- Repair minor erosion areas observed in photos 9710, 9718, and 9729.
- Treat fire ant mounds observed near approximate station 88+00 as shown in photo 9560 and repair area as appropriate. Implement regular fire ant control activities throughout the dike system.
- Replace the existing staff gauge with one that extends lower to capture low impoundment elevations. Reconcile staff gauge with dike spillway elevations.

Mr. Robert Stevens  
May 15, 2018  
Page 2 of 2


BBA appreciates the opportunity to assist Coletto Creek Power with this project. If you have any questions regarding this inspection report, or if we can be of further assistance, please call us at (512) 355-9198.

Sincerely,

Bullock, Bennett & Associates, LLC



Dan Bullock, P.E.  
Attachments



5/15/18

---

Texas PE No. 82596  
Texas Engineering Firm Registration No. F-8542

**ATTACHMENT A**

**Inspection Report**

# Dam Inspection Report

Name of Dam Primary Ash Pond Dam ID No. 141

Permit Number NA Class of Dam Intermediate/Low Hazard

Location            Section            Township            Range           

Owner Coletto Creek Power, LP 800-633-4704  
Name Telephone Number (Day)

45 FM 2987 same  
Street Telephone Number (Night)

Fannin 77905 County Goliad  
City Zip Code

Type of Dam Earth Embankment

Type of Spillway Decant Weir Structure


Date(s) Inspected 20-Dec-17

Weather When Inspected Pt. Cloudy

Temperature When Inspected Approx. 70 deg F

Pool Elevation When Inspected Approx. 127 ft MSL (below lowest demarcation of 128.0)

Tailwater Elevation When Inspected NA



Professional Engineer's Seal

## Inspection Personnel:

Bullock, Bennett & Associates, LLC  
Dan Bullock Principal Engineer

Name Title

Coletto Creek Power, LP  
Rick Coleman EHS Coordinator

Name Title

Dynegy Inc.  
Jason Campbell Dam Safety Manager

Name Title

Dynegy Inc.  
Bruce Birbeck Environmental Manager - ERCOT

Name Title

The Department of Natural Resources is requesting information that is necessary to accomplish the statutory purpose as outlined under the River, Lakes and Streams Act, 615

ILCS 5. Submittal of this information is REQUIRED. Failure to provide the required information could result in the initiation of non-compliance procedures as outlined in

Section 3702.160 of the "Rules for Construction and Maintenance of Dams".

### CONDITION CODES

- NE - No evidence of a problem
- GC - Good condition
- MM - Item needing minor maintenance and/or repairs within the year, the safety or integrity of the item is not yet imperiled
- IM - Item needing immediate maintenance to restore or ensure its safety or integrity
- EC - Emergency condition which if not immediately repaired or other appropriate measures taken could lead to failure of the dam
- OB - Condition requires regular observation to ensure that the condition does not become worse
- NA - Not applicable to this dam
- NI - Not inspected - list the reason for non-inspection under deficiencies

## EARTH EMBANKMENT

ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE
Surface Cracks	NE		
Vertical and Horizontal Alignment of Crest	NE		
Unusual Movement or Cracking At or Beyond Toe	NE		
Sloughing or Erosion of Embankment and Abutment Slopes	NE		
Upstream Face Slope Protection	MM	Generally in good condition but minor erosion was observed along the north dike below existing rip rap.	If low water surface elevations are to be maintained long term, consider extending riprap further down slope to an elevation of approximately 3' lower than water surface.
Seepage	OB	Moist areas observed between Sta 84+00 to 90+00. No flow or ponding observed and appeared to be considerably drier and less extensive than 2016.	Continue monitoring for changes that would indicate seepage is worsening. Area lacked vegetation and appeared to have minor and surficial hog damage that should be addressed.
Filter and Filter Drains	GC	There are no internal chimney drains within the dike system. The existing seepage collection system was visually inspected to verify it was operational.	

## **EARTH EMBANKMENT**

(Continued)

ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE
Animal Damage	MM	Evidence of minor animal rooting/grubbing observed in sporadic locations. Possible animal burrows near Sta 38+00. Fire ant mounds observed near Sta 88+00.	Use compacted earth fill in animal burrows as necessary. Animal and fire ant control should be implemented as necessary.
Embankment Drainage Ditches	NA		
Vegetative Cover	GC	Generally in good condition except as noted between Sta 84+00 and 90+00.	
Staff Gauge	MM	Water level below lowest demarcation. Staff gauge elevation approximately 0.4 ft above actual NAVD88 elevation.	Replace existing staff gauge with one that extends lower to capture low impoundment elevations. Reconcile staff gauge with survey elevations.
Piping	MM	Several pipes penetrate the top 2 to 3 ft of the dike. One near Sta 70+00 appears to be crushed at the outlet.	Consider removing any piping that is not in use, and completing internal inspections (with use of remote camera) for pipes that will remain.
Other			
Other			

**OUTLET WORKS**  
**IF SEPARATE FROM PRINCIPAL SPILLWAY STRUCTURE**

ITEM	CONDITION CODE	DEFICIENCIES	RECOMMENDED REMEDIAL MEASURES AND IMPLEMENTATION SCHEDULE
Erosion, Spalling, Cavitation	NE		
Joint Separation	NA		
Seepage Around or Into Conduit	NA		
Intake Structure	NI	Weir structure intake was submerged and therefore could not be inspected.	
Outlet Structure	NI	The outlet structure is located below the water level of the Secondary Pond and therefore could not be inspected.	
Outlet Channel	NA		
Riprap	NA		
Walkway	GC		
Other			

SUMMARY OF MAINTENANCE DONE AND/OR  
REPAIRS MADE SINCE THE LAST INSPECTION

DATE OF PRESENT INSPECTION 20-Dec-17

DATE OF LAST INSPECTION 14-Dec-16

## 1. EARTH EMBANKMENT DAMS

Placed earth fill in localized hog rooting areas, cut the grass and treated site for ants.

## 2. CONCRETE MASONRY DAMS

### 3. PRINCIPAL SPILLWAY


#### 4. OUTLET WORKS

Repaired loose hand rails, and repaired sign supports near the walkway.

## 5. EMERGENCY SPILLWAY

**ATTACHMENT B**

**Inspection Site Plan and Photographs**




APPROXIMATE SCALE: 1" = 400'



**EXPLANATION**

- 2276 PHOTO # AND DIRECTION OF PHOTO
- 50+00 PRIMARY ASH POND STATIONING



*Daniel B. Bullock*  
5-15-2018

SOURCE: AERIAL PHOTO PROVIDED BY IMAGEPATCH.COM EARTHSTAR GEOGRAPHICS, DATE: MAY-OCT 2011.

**Coletto Creek Power, LP**

Figure 1  
**PRIMARY ASH POND  
DIKE INSPECTION  
(December 2017)**

PROJECT: 16244 BY: RR DATE: MAY 2018 CHECKED: DBB

**Bullock, Bennett & Associates, LLC**  
Engineering and Geoscience  
Texas Registrations: Engineering F-8542, Geoscience 50127




9516 - Exterior / Pipe Corridor



9517 - Exterior



9522 - Top of Levee / Exterior



9526 - Top of Levee



9534 - Exterior




9538 - Interior




9539 - Interior Slope Protection



9551 - Exterior, Hog Damage




9560 - Exterior, Fire Ant Mounds



9563 - Exterior, Apparent Seep Area



9574 - Exterior



9577 - Exterior, Apparent Seep Area

# NOMENCLATURE

"Interior" means interior side slope of Primary Ash Pond dike.



*Daniel B. Bullock*  
5-15-2018


Coleto Creek Power, LP

FIGURE 2  
PRIMARY ASH POND  
DIKE INSPECTION  
(December 2017)

PROJECT: 15-202 BY: RJR DATE: MAY 2018 CHECKED: DBB

Bullock, Bennett & Associates, LLC

Engineering and Geoscience  
Texas Registrations: Engineering F-8542, Geoscience 50127




9578 - Exterior, Piezometer




9584 - Interior



9585 - Interior Slope Protection



9589 - Interior Slope



9633 - Top of Levee, Dike Interior



9636 - Pipe Penetration




9641 - Outlet Works




9644 - North Dike Interior, Erosion Below Slope Armor




9645 - North Dike Interior, Erosion Below Slope Armor



9649 - Stoplog Slots




9653 - Outlet Works




9710 - Exterior Erosion, Burrow

NOMENCLATURE


"Interior" means interior side slope of Primary Ash Pond dike.



Coletto Creek Power, LP			
FIGURE 3 PRIMARY ASH POND DIKE INSPECTION (December 2017)			
PROJECT: 15-202	BY: RJR	DATE: MAY 2018	CHECKED: DBB
Bullock, Bennett & Associates, LLC			
Engineering and Geoscience			
Texas Registrations: Engineering F-8542, Geoscience 50127			



9715 - West Dike Exterior / Evaporation Pond



9729 - Interior Erosion



9647 - Staff Plate on Outlet Works



9718 - Exterior Erosion,  
Possible Borrow Near Toe



9642 - Primary Ash Pond / Secondary Pond  
Separator Dike




9659 - Discharge from Primary Ash Pond  
to Secondary Pond



9672 - Pipe Discharge to Evaporation Pond

# NOMENCLATURE

"Interior" means interior side slope of Primary Ash Pond dike.



Coleta Creek Power, LP			
<p>FIGURE 4 PRIMARY ASH POND DIKE INSPECTION (December 2017)</p>			
PROJECT: 15-202	BY: RJR	DATE: MAY 2018	CHECKED: DBB
<p>Bullock, Bennett &amp; Associates, LLC Engineering and Geoscience Texas Registrations: Engineering F-8542, Geoscience 50127</p>			