Written By: Z. Fallert, P.E. Reviewed By: N. Higgerson



2022 Annual Coal Combustion Residuals (CCR) Landfill Inspection Report			
Site Name:	Hennepin Power Plant		
Site Address:	13498 E. 800th Street, Hennepin, IL 61327		
Owner/Operator:	Dynegy Midwest Generation, LLC		
Owner/Operator Address:	13498 E. 800th Street, Hennepin, IL 61327		
CCR Unit:	CCR Landfill		

## 40 C.F.R. § 257.84 INSPECTION REQUIREMENTS FOR CCR LANDFILLS

## (b) ANNUAL INSPECTIONS BY A QUALIFIED PROFESSIONAL ENGINEER

- (1) Existing and new CCR Landfills and any lateral expansion of a CCR landfill must be inspected on a periodic basis by a qualified professional engineer to ensure that the design, construction, operation, and maintenance of the CCR unit is consistent with recognized and generally accepted good engineering standards. The inspection must, at a minimum, include:
  - (i) A review of available information regarding the status and condition of the CCR unit, including, but not limited to, files available in the operating record (e.g., the results of inspections by a qualified person, and results of previous annual inspections); and

Qualified person inspection documentation (weekly inspection reports) and previous annual inspection reports were reviewed. (ii) A visual inspection of the CCR unit to identify signs of distress or malfunction of the CCR unit.

A visual inspection was performed by Zachary J. Fallert, P.E. on October 5, 2022. The inspection included the CCR surface, stormwater collection system, and perimeter roads.

- (2) INSPECTION REPORT. The qualified professional engineer must prepare a report following each inspection that addresses the following:
  - (i) Any changes in geometry of the structure since the previous annual inspection;

Based on available plant records and visual observation, the geometry of the landfill has not been changed since the previous inspection.

(ii) The approximate volume of CCR contained in the unit at the time of the inspection;

This unit has not received CCR or other permitted wastes since the previous inspection. Approximately 7000 cubic yards of CCR material were reportedly placed during construction over the geomembrane liner as freeze protection for the liner system.

(iii) Any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit; and

No signs of structural weakness in the CCR landfill or conditions that have the potential to disrupt operation of the landfill were identified in the visual inspection or in the weekly inspection reports. Minor silting in of stormwater culverts was observed which is corrected through normal and regular maintenance. The landfill surface is vegetated and is regularly mowed. Damage to the exposed geomembrane liner was observed at one location and will be repaired by plant personnel.

(iv) Any other change(s) which may have affected the stability or operation of the CCR unit since the previous annual inspection.

Based on available plant records and visual observation, no changes were observed that are expected to impact stability or operation of the CCR unit.

I, Zachary J. Fallert, being a Registered Professional Engineer in good standing in the State of Illinois, do hereby certify, to the best of my knowledge, information, and belief, that the information contained in this CCR landfill certification report has been prepared in accordance with the accepted practice of engineering and the requirements of 40 C.F.R. § 257.84(b).

Zachary J. Fallert		
Printed Name		
Feelray Fella		11/21/2022
Signature		Date
062-073263	IL	11/30/2023
Registration Number	State	Expiration Date