## ANNUAL CCR SURFACE IMPOUNDMENT INSPECTION REPORT (per 40 CFR 257.83(b)(2))

Power Station: Newton Power Station

Owner: Illinois Power Generating Company

CCR Impoundment: Primary Ash Pond

Date of Inspection: 8/18/2016

Name of Qualified Professional Engineer: James Knutelski, P.E. and Jason Campbell, P.E.

In accordance with 40 CFR § 257.83(b)(1), an existing or new CCR surface impoundment or any lateral expansion of the CCR surface impoundment that is subject to the periodic structural stability assessment requirements under § 257.73(d) or § 257.74(d) must be inspected on a periodic basis (annually per 40 CFR § 257.83(b)(4)) by a qualified professional engineer to ensure that the design, construction, operation, and maintenance of the CCR unit is consistent with recognized and generally accepted good engineering standards. The inspection must, at a minimum, include: (i) A review of available information regarding the status and condition of the CCR unit, including, but not limited to, files available in the operating record (e.g., CCR unit design and construction information required by §§ 257.73(c)(1) and 257.74(c)(1), previous periodic structural stability assessments required under §§ 257.73(d) and 257.74(d), the results of inspections by a qualified person, and results of previous annual inspections); (ii) A visual inspection of the CCR unit to identify signs of distress or malfunction of the CCR unit and appurtenant structures; and (iii) A visual inspection of any hydraulic structures underlying the base of the CCR unit or passing through the dike of the CCR unit for structural integrity and continued safe and reliable operation.

## Inspection Report 40 CFR § 257.83(b)(2)

The inspection included a review of available information regarding the status and condition of the CCR unit, including, but not limited to, files available in the operating record, previous periodic structural stability assessments required under §§ 257.73(d) (if any), and the results of inspections by a qualified person and previous annual inspections; a visual inspection of the CCR unit to identify signs of distress or malfunction of the CCR unit and appurtenant structures; and a visual inspection of hydraulic structures (if any) underlying the base of the CCR unit or passing through the dike of the CCR unit for structural integrity and continued safe and reliable operation.

Based on the inspection, the design, construction, operation, and maintenance of the CCR unit is consistent with recognized and generally accepted good engineering standards. The following information is provided in accordance with 40 CFR § 257.83(b)(2).

i) Have there been any changes in geometry of the impounding structure since the previous annual inspection? If yes, please explain.

Based on a visual inspection of the impoundment and any hydraulic structures present, as well as a review of previous inspection report there are no changes.

ii) Instrumentation (Please see following page for instrumentation location map)

Instrument ID#	Туре	Maximum recorded reading since previous annual inspection (ft)
See Attached		

		Approximate Depth / Elevation					
iii) Since previous		Elevation (ft)			Depth (ft)		
	annual inspection:	Minimum	Present	Maximum	Minimum	Present	Maximum
	Impounded Water		539		19	4	
	CCR	515		545	33	63	45

- iv) Storage capacity of the impounding structure at the time of the inspection (acre-ft): 31000
- v) Approximate volume of the impounded water and CCR at the time of the inspection (acre-ft):13060
- vi) Are there any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit and appurtenant structures?

1				
	N	0	n	-
	·	U		

vii) Are there any other changes which may have affected the stability or operation of the impounding structure since the previous annual inspection?

N	or	16

I, James Knutelski, P.E, certify under penalty of law that the information submitted in this report was prepared by me or under my direct supervision and that I am a duly Registered Professional Engineer under the laws of the state of Illinois. The information herein is to the best of my knowledge and belief, true, accurate and complete.



Instrument ID #	Туре	Maximum recorded reading since previous annual inspection (ft)		
B001	Piezometer	509.2'		
B003	Piezometer	519.6'		
B004	Piezometer	550.0'		
B005	Piezometer	537.7'		
B006	Piezometer	539.3'		
B007	Piezometer	549.7'		
B008	Piezometer	535.0'		
B009	Piezometer	526.9'		
B010A	Piezometer	539.8'		
B010B	Piezometer	526.9'		
B012	Piezometer	519.1'		
B014	Piezometer	507.1'		
B015	Piezometer	535.5'		
B016	Piezometer	510.4'		

