CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| Station | Edwards | | | Dat | e: 2/1/3 | 2022 | | | |
|---|--|-------|--------------------------|--|--------------------------------------|----------------------------|------------|----------------|--|
| Impoundment Name: As | | | | Tim | e: pg:p/ | 2 | t | | |
| | : W143805000 | 5-01 | - | Inspector(s | 01.00 | Koller | į. | | |
| Sky: Heavy Temp. | : 41°F | - ' | Precip. (last 48 hrs): | 0.0 | F | Pool Elev.: | 40 | 447.5 | |
| "YES" responses require description at the time of inspection. If "ACTIO additional sheets as necessary. Circ | N" selected is "INVE | STIGA | TE", please indicate dat | CRIPTION" section. "NO" te forwarded via email to (| response indicate Dam Safety Mana | es no issues vager (DSM) . | vere o | bserved | |
| ITEM | | | | | | ACTION | | | |
| | | NO | | DESCRIPTION | | MONITOR | NVESTIGATE | SENT TO DSM | |
| CREST | General Condition | Goog | / Fair / Poor | Repairs: | Date: | | 100 | | |
| Cracking | | V | 1 | | | | | | |
| Settlement | | L | | | | | | 35 | |
| Erosion Rills | | 1 | | | | | | | |
| Animal Burrows | | V | 1 | | | | | | |
| Misalignment | | / | 1 | ···· | | | | | |
| Vegetation (greater than 12" |) | 1 | | | | | | 11.22 | |
| UPSTREAM EMBANKMENT | General Condition | Good | / Fair / Poor | Repairs: | Date: | | Miss I | | |
| Cracking | | V | 1 | | | | | | |
| Sloughing / Bulging | | V | | | | | | | |
| Seepage | | V | | · . | | | | | |
| Sink Holes | | 1/ | | · · · · · · · · · · · · · · · · · · · | | | | \Box | |
| Animal Burrows | | 1 | | . | | | | \Box | |
| Erosion Rills | | | | | | \neg | | | |
| Slope Protection / Rip Rap | | | | | | | | | |
| Vegetation (greater than 12" | | V | | | | | | | |
| DOWNSTREAM EMBANKMENT | | Good | Fair / Poor | Repairs: | Date: | (20 Ed. 2) | | 13-24 | |
| Cracking | · | V | | | | | | | |
| Sloughing / Bulging | | 1 | | · · · | | | | | |
| Seepage | | ~ | | | | | | | |
| Sink Holes | | V | | | | | | | |
| Sand Boils (indicate if flowing and color) | | V | | | ···· | | | \Box | |
| Animal Burrows | | | | | | | | \vdash | |
| Erosion Rills | | 1 | , | | | \dashv | | \square | |
| Vegetation (greater than 12") | | V | | <u>.</u> | | \dashv | | | |
| SPILLWAY(S) | General Condition | Good | / Fair / Poor | Repairs: | Date: | | 大石市 | | |
| Actively Flowing (provide de | A STATE OF THE PARTY OF THE PAR | | 2 1-1.5 | | to the second | | | | |
| Obstructions Present | | | 75 / 7.0 | | | _ | | | |
| Seepage | | V | | | | | | | |

Sand Boils (indicate if flowing and color)

Erosion Rills