CCR Impoundment Weekly Inspection

| | 35 I | LL. A | ADM. Code 845 / 4 | CFR Part 257 | | , | | |
|---|-----------------------|------------|--------------------------|--------------------|---------------------------|-------------|-------------|----------------|
| Station: | Edwards | | | | Date: ////6/ | 2022 | | |
| Impoundment Name: Ash Po | | | - | | Time: 10:30 | AM | • | |
| · | W1438050005 | 5-01 | | Inspe | ector(s): Rick | Kelle | 24 | |
| Cloudy | | | - | • | TCIL. | TCC / K | 7 | |
| Sky: W/Snow Temp.: | 30°F | - | Precip. (last 48 hrs): | 0.03" | Pod | ol Elev.: | 4 | 47.3 |
| | | • | | | | | | |
| "YES" responses require description | (size, depth, extents | , colc | or) and location in "DES | CRIPTION" section. | "NO" response indicates r | no issues v | were o | bserved |
| at the time of inspection. If "ACTION | | | | e forwarded via en | nail to Dam Safety Manage | r (DSM) . | Attach | i |
| additional sheets as necessary. Circle General Conditio | | for e | ach section. | - | | 4.071011 | | |
| ITEM | | | DESCRIPTION | | | ACTION | | |
| | | NO | | | | MONITOR | INVESTIGATE | SENT TO DSM |
| CREST | General Condition | 3000 | P/ Fair / Poor | Repairs: | Date: | | HAR | |
| Cracking | | V | | | 101010 | | | |
| Settlement | | V | 1 | | | | | |
| Erosion Rills | | V | , | T-0000 | | | | |
| Animal Burrows | | 1 | | , | | | | |
| Misalignment | | V | 1 | | | | | |
| Vegetation (greater than 12") | | V | | | | | | |
| UPSTREAM EMBANKMENT | General Condition: | 6000 | Fair / Poor | Repairs: | Date: | | | |
| Cracking | | / | .1 | | | | | |
| Sloughing / Bulging | | V | | *· 10 | | | | |
| Seepage | | | | | | | | |
| Sink Holes | | V | | | | | | |
| Animal Burrows | | / | | | | | | |
| Erosion Rills | | V | | | | | | |
| Slope Protection / Rip Rap | | | / | | | | | |
| Vegetation (greater than 12") | | / | | | | | | |
| DOWNSTREAM EMBANKMENT General Condition | | G000 | D/ Fair / Poor | Repairs: | Date: | | | |
| Cracking | | | | 5.40 | | | | |
| Sloughing / Bulging | | | 1 | | | | | |
| Seepage | | V | | | | | | Ш |
| Sink Holes | | L, | | | | | | |
| Sand Boils (indicate if flowing and color) | | V | | | | | | |
| Animal Burrows | | 1 | | | | \perp | | |
| Erosion Rills | | 1 | | | - | | | |
| Vegetation (greater than 12") | | V | | | | | | Щ |
| SPILLWAY(S) | General Condition: | 6000 | | Repairs: | Date: | | | |
| Actively Flowing (provide de | pth) | • | ≈ 1.0" | | | | | |
| Obstructions Present | | <u>/</u> | | | | | | Ш |
| Seepage | | / | ļ | | | \perp | | \sqcup |
| Sand Boils (indicate if flowing and color) | | V | | | | | | |
| Erosion Rills | | V | | | | | | \square |
| PERIMTER FENCING/GATES | | Gào | //Fair / Poor | Repairs: | Date: | | | |
| Evidence of damage or tar | npering | \ <u>\</u> | | | | 1 7 | | |

New chains added @ \$ gates

Evidence of unauthorized access

Gates closed and locked