CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| i, | | 33 ILL | ADM. Code 845 / 4t | CFR Part 257 | | |
|-------------------------------------------------------|------------------|-----------------------|----------------------------|-----------------------------|----------------------------|-------------------------|
| | Station: | Joppa | Date: | 4-20-22 | • | |
| Impoundmei | | | nd | Time: | 10:39 | |
| IEPA | Number: <u>(</u> | 11270100002 | 1-02 | inspector(s): | RFainhn | |
| Sky: OverCast | Temp.: | 64% | Precip. (last 48 hrs): | 0" | Pool Elev.: | 4.82 |
| YES ^a responses require o | description (siz | ze, depth, extents, o | olor) and location in "DES | CRIPTION" section. "NO" re- | enonce indicatos no legue- | 1 11 |
| t the time of inspection, dditional sheets as nece | If "ACTION" s | elected is "INVESTI | GATE", please indicate dat | e forwarded via email to Da | m Safety Manager (DSM) | vere observec Attach |

| ITEM | | | · | | ACTION | | |
|---------------------------------------------------------------------|----------|---------------------------------------|---------------------------------------|--------------------------------------------------|--------------------------------------------------|----------------|--|
| | | NO | DESCRIPTION | MONITOR | INVESTIGATE | SENT TO DSM | |
| CREST General Con | ditlon: | Good | / Fair / Poor Repairs: Date: | | 10 W 10 W | | |
| Çracking | | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | | |
| Settlement . | | | | **** | | 4 5 6 | |
| Erosion Rills | | V | | | , | | |
| Animal Burrows | | V | | ٠. | | 1.00 | |
| Misalignment | | . 🗸 | | | | | |
| egetation (greater than 12") | <u> </u> | V | | | • | | |
| TREAM EMBANKMENT General Condition; Good) Fair / Poor Repairs Date: | | | | | | 新育宗 | |
| Cracking . | | V | | | | | |
| Sloughing / Bulging | | V | | | | | |
| Seepage | | V | | , | | | |
| Sink Holes | <u> </u> | / | | | 7 | - | |
| Animal Burrows | | V | | | | | |
| Erosion Rills | | V | | | | | |
| Slope Protection / Rip Rap | | V | | | , | | |
| Vegetation (greater than 12") | 1 | | Deal Vojetation at water line. | <u> </u> | | | |
| DOWNSTREAM EMBANKMENT General Conc | lition!(| Good | Fair / Poor Repairs: Date: | 13124 (131 11124 (1314 | Asia. | | |
| Cracking | | | | *************************************** | | - 1 | |
| Sloughing / Bulging | | V | | - | | | |
| Seepage | | | 3 | | | | |
| Sink Holes | | 1 | | · | <u> </u> | ļ | |
| Sand Boils (Indicate if flowing and color) | | V | | <u> </u> | | | |
| Animal Burrows | | 1 | , , , , , , , , , , , , , , , , , , , | · | 1 | | |
| Erosion Rills | | 7 | | | | | |
| Vegetation (greater than 12") | | V | | | | | |
| SPILLWAY(S) General Cond | ttjön:/ | sood | Fair / Poor Repairs: Date: | 10.23 | -8820 | | |
| Actively Flowing (provide depth) | ~ | | 5" nater Flow at outfall structure. | - 000 CO | g.2961 (2.0% | 1 2 3 5 5 | |
| pstructions Present | | ~ | All - Million Million . | | - | | |
| eepage | | | | | | - | |
| Sand Boils (indicate if flowing and color) | | V | | 1 | | | |
| Erosion Rills | | ~ | | | | ╁ | |