CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	Station:	Joppa	*	Date:	8-3-22	Ÿ
Impoun	dment Name:	East Ash	Pond	Time:	10:08	
IEPA Number: 61270(0000)			04-02	Inspector(s):	R Favaha	
Sky: Clear	Temp.:	87°1=	Precip. (last 48 hrs):	1.19	Pool Elev.:	4.52

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ACTION

					ACTIO	IN
ITEM		NO	DESCRIPTION	MONITOR	NVESTIGATE	SENT TO DSM
CRÉST General Cor	dition	Goo	Fair / Poor Repairs: Date:			N D
Cracking		V		200 TO 200 TO 2012	100000000000000000000000000000000000000	(0.08/390.9
Settlement		V			<u> </u>	27.1
Erosion Rills		V				(5 ***
Animal Burrows		V				
Misalignment		L				<u> </u>
egetation (greater than 12")	7	~				
TREAM EMBANKMENT General Con	dition:	Good	Fair / Poor Repairs: Date:			A DE
Cracking		V				350E-55
Sloughing / Bulging		V				<u> </u>
Seepage		V				<u> </u>
Sink Holes		V				-
Animal Burrows		V				
Erosion Rills		V			-	-
Slope Protection / Rip Rap		V			_	2 1
Vegetation (greater than 12")	V		bent vectation at water line.		-	1
DOWNSTREAM EMBANKMENT General Con	dition	Good	/ Fair / Poor Repairs: Date:			
Cracking		V	The state of the s			3556.70
Sloughing / Bulging		V				-
Seepage		V			-	-
Sink Holes		V			-	-
Sand Boils (indicate if flowing and color)		V			-	+
Animal Burrows		V			 	-
Erosion Rills		/			-	
Vegetation (greater than 12")	V		Grass on Slupe.		-	7
	dition:	Good	Fair / Poor Repairs: Date:		10000	7.20 May 2
Actively Flowing (provide depth)	1		5" water flow at outfall structure.		12702 1976	25.60
bstructions Present	\Box	V	2 Orbert 1 MM Car On 1 And 2 1 1 MM La		-	+
eepage		V	V	-		-
Sand Boils (indicate if flowing and color)		V			├	+
Erosion Rills		V			-	-

1 1 1