CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| Station: Joppa | • | | Date: ﴿ ﴿ كَانِهُ الْعَامِينَ الْعَامِينَ الْعَامِينَ الْعَامِينَ الْعَامِينَ الْعَامِينَ الْعَامِينَ الْعَامِ | | | , | |
|--|-------------|---------------|--|--------------|------------|----------------|--|
| Impoundment Name: East A | | Time: | | | | | |
| IEPA Number: <u>W1270</u> | 1000 | 24 - | | | | | |
| Ciaro | <u>oca</u> | <u>- L - </u> | mspector(s). | | | | |
| - Sky: <u>Code</u> Temp.: <u>6599</u> | | . P | recip. (last 48 hrs): C.C.> Pool E | Pool Elev.: | | 2.33 | |
| "VES" responses require description (size, depth | ovtant | s colo | r) and location in "DESCRIPTION" section. "NO" response indicates no | | | | |
| at the time of inspection. If "ACTION" selected is | "INVES | STIGA | TP and location in Description section. "NO" response indicates no TE", please indicate date forwarded via email to Dam Safety Manager (I | issues i | were of | oservec | |
| additional sheets as necessary. Circle General Co | ndition | for e | ach section. | | riciacii | . : | |
| | | | | ACTION | | 1 | |
| ITEM | YES | NO | DESCRIPTION | MONITOR | NVESTIGATE | SENT TO DSM | |
| CREST General Con | dition | Good | /sFair / Poor Repairs: Date: | | <u>-</u> | 8 0 | |
| Cracking | _ | 10 | | | | | |
| Settlement | | 2 | | | | | |
| Erosion Rills | | | | | | | |
| Animal Burrows | | 2 | , | | | | |
| Misalignment | ļ | | | | | | |
| egetation (greater than 12") | ********** | The sections | | nacrosa in a | | | |
| CONTREAM EMBANKMENT General Con | dition: | Good | / Fair / Poor Repairs: Date: | | | 著艺法 | |
| Cracking | | | | | | | |
| Sloughing / Bulging | | | | | | | |
| Seepage | ļ | | | | | | |
| Sink Holes | | | | | | | |
| Animal Burrows | ļ | | | | | | |
| Erosion Rills | | ~ | | | | 2 2 | |
| Slope Protection / Rip Rap | | <u>.</u> | | | | | |
| Vegetation (greater than 12") | 32° | <u> </u> | Alle agetas whise is he was inc. | | | | |
| DOWNSTREAM EMBANKMENT General Con | dition; | Good | / Fair / Poor Repairs: Date: | 製造 基礎 | | 38 (1) | |
| Cracking | | 1 | | | | | |
| Sloughing / Bulging | | 1,000 | | | | | |
| Seepage | | | | | ļ | | |
| Sink Holes | | 2 | | | <u> </u> | <u> </u> | |
| Sand Boils (indicate if flowing and color) | | レ | | <u> </u> | <u> </u> | | |
| Animal Burrows | | し | | <u> </u> | 1 | | |
| Erosion Rills | | | | | | | |
| Vegetation (greater than 12") | L. | | Strange Strang | | | 1 | |
| SPILLWAY(S) General Con | dition; | Good | Fair / Poor Repairs: Date: | 783 | | | |
| Actively Flowing (provide depth) | 3 22 | | 18 Lance Through wife | | | | |
| ostructions Present | | 2. | | | | | |
| Seepage Seepage | | U | | | | | |
| Sand Boils (indicate if flowing and color) | | ン | | | | | |

Erosion Rills