

JAN/01/2020

KINGAID GENERATION, L.L.C. PROCEDURE

Huber

Sangchris Lake Dam and Dike Minor Inspection

TS-GEN-0-005

LAST REVISED BY:
Richard Dixon

LAST REVISION DATE:
11-12-15

Rev.
1

Page 4 of 6

Attachment A
MONTHLY DAM INSPECTION

Date: 11/02/22 Weather Observations: Sunny 72°

| ITEMS TO BE INSPECTED ON THE DAM | NORMAL | ABNORMAL | COMMENTS |
|---|--------|----------|----------|
| 1 Wet areas or seepage on dam | ✓ | | |
| 2 Seepage on West downstream slope | ✓ | | |
| 3 Erosion, holes & evidence of burrowing animals | ✓ | | |
| 4 Condition of riprap on upstream slope | ✓ | | |
| 5 Grass cover on downstream slope | ✓ | | |
| 6 Trees and bushes growing on slopes | ✓ | | |
| 7 Condition of road and drain gutters | ✓ | | |
| 8 Elevation of dam settlement device | ✓ | | |
| 9 Elevation of water in settlement device | ✓ | | |
| 10 Condition of service spillway concrete structure | ✓ | | |
| 11 Condition of service spillway fence and posts | ✓ | | |
| 12 Condition of service spillway riprap | ✓ | | |
| 13 Trees and bushes on Auxiliary spillway | ✓ | | |
| 14 Grass cover on Auxiliary spillway | ✓ | | |
| 15 Erosion of Auxiliary spillway | ✓ | | |

| MEASUREMENTS | ELEVATION | TEMPERATURE | COMMENTS |
|-------------------|-----------|-------------|----------|
| 16 Sangchris Lake | 584.5 | 59.9 | |
| 17 Well #1 | 576.7 | 69.8 | |
| 18 Well #2 | 575.6 | 64.4 | |
| 19 Well #3 | 572.2 | 60.8 | |
| 20 Well #8 | 524 | N/A | |

| FLOW OBSERVATION | FLOW | TEMPERATURE | COMMENTS |
|-----------------------|---------|-------------|----------|
| 21 Well #7 | No Flow | N/A | |
| 22 West Slope Seepage | Normal | 68.0 | |

Summary of Maintenance Required:

Inspected By: Dave Huber

Date: 11/02/22