CCR Impoundment Weekly Inspection ** 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid	emmua	Wednesday Lines	6/28/23
Impoundment Name:		4	Time: Inspector(s): 人	Huxu
IEPA Number:	W0218140002-0	<u> </u>	Cranscondin	no manda de la companya del companya de la companya del companya de la companya d
sky: Smoken Temp .:	75°F	Precip. (last 48 hrs):		Pool Elev.: - 26
		and the state of t		

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM							ACTIO	N
		NO	DESCRIPTION			RONITOR	INVESTIGATE	SENT TO DSM
CREST G	eneral Condition	Good	Fair / Poor	Repairs:	Date:			
Cracking	·	W	A CONTRACTOR OF THE PROPERTY O	Charles (MALANIC CONTINUES OF A TOTAL CONTINUES OF	Additional transport projects (III) a type sink a little and the state of the state	Wind with the same of the same		
Settlement		V						
Erosion Rills		[V						
Animal Burrows		V				ALEXANDER SERVICE CONTRACTOR		
Misalignment		V		The second secon	THE COURT OF THE C			-
Vegetation (greater than 12")		1/		The state of the s	The state of the s			-
UPSTREAM EMBANKMENT G	eneral Condition	: 6 00d	Fair / Poor	Repairs:	Date:			
Cracking		A		1110			<u> </u>	
Sloughing / Bulging	AND DESCRIPTION OF THE PARTY OF	1	CONTRACT OF THE PARTY OF THE PA	The state of the s	A SAN COMMENT OF THE PROPERTY			
Seepage		1						
Sink Holes		N						<u> </u>
Animal Burrows		12		· .				
Erosion Rills		14/			and the second s		<u> </u>	-
Slope Protection / Rip Rap		V			<u> </u>			
Vegetation (greater than 12").		<u> </u>	AND THE PROPERTY OF THE PROPER	**************************************	The second secon			
DOWNSTREAM EMBANKMENT G	eneral Condition	: 6000	Poor	Repairs:	Date:			-
Cracking		V			MALE CONTRACTOR OF THE CONTRAC			
Sloughing / Bulging		V						
Seepage		\ \\ \\ \/	4		deligner			
Sink Holes		1/					-	
Sand Boils (indicate if flowing an	nd color)			160000		-	 	-
Animal Burrows	√	<u> </u>	FINSIN	g / FILLING			<u> </u>	-
Erosion Rills	System of the second se	V	and the same of th	- A Photo and the second secon	one of the state o			
Vegetation (greater than 12")	,	<u> </u>	,	- Mariana - Mari	graph and the second			1
SPILLWAY(S) G	ieneral Condition	ı: (600)	// Fair / Poor	Repairs:	Date:			
	h)	Name of Street, or other Persons		алу аталапты афті (Алтандагот ангалу Феріфу частала іспанізтика у фудмання ангалу				
Obstructions Present		V						
Seepage		V						
Sand Bolls (indicate if flowing ar	nd color)	1						_
Erosion Rills		V		1	V			<u>l</u>