

KINCAID GENERATION, L.L.C. PROCEDURE

Sangchris Lake Dam and Dike Minor Inspection

TS-GEN-0-005

LAST REVISED BY:
Richard Dixon

LAST REVISION DATE:
11-12-15

Rev.
1

Page 4 of 6

Attachment A MONTHLY DAM INSPECTION

Date: 2/8/24 Weather Observations: Cloudy 45 F

ITEMS TO BE INSPECTED ON THE DAM		NORMAL	ABNORMAL	COMMENTS
1	Wet areas or seepage on dam	✓		
2	Seepage on West downstream slope	✓		
3	Erosion, holes & evidence of burrowing animals	✓		
4	Condition of riprap on upstream slope	✓		
5	Grass cover on downstream slope	✓		
6	Trees and bushes growing on slopes		✓	NEEDS ATTENTION
7	Condition of road and drain gutters		✓	NEEDS ATTENTION
8	Elevation of dam settlement device	✓		
9	Elevation of water in settlement device	✓		
10	Condition of service spillway concrete structure	✓		
11	Condition of service spillway fence and posts	✓		
12	Condition of service spillway riprap	✓		
13	Trees and bushes on Auxiliary spillway	✓		
14	Grass cover on Auxiliary spillway	✓		
15	Erosion of Auxiliary spillway	✓		
MEASUREMENTS		ELEVATION	TEMPERATURE	COMMENTS
16	Sangchris Lake	585.3'	43.9 F	
17	Well #1	576.4'	61.9 F	
18	Well #2	575.6'	57.6 F	
19	Well #3	572.3'	51.8 F	
20	Well #8	562.6	Dry	Dry Well
FLOW OBSERVATION		FLOW	TEMPERATURE	COMMENTS
21	Well #7	No Flow	N/A	
22	West Slope Seepage	NORMAL	53.6 F	

Summary of Maintenance Required:

6. TREES / BRUSH NEEDS REMOVED ON LAKE SIDE OF SLOPE.
7. ROADWAY GUTTER NEEDS REPAIRED

Inspected By:

[Signature]

Date:

02/08/24