## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Impoundment Name: IEPA Number:		Newtor	1	Date	4/19/2023	
		Primarry Ash Pond W0780700001-01		Time: Inspector(s):	2:45 PM Terry Hanratty	
Sky: Overcast	Temp.:	79	Precip. (last 48 hrs):	0	Pool Elev.:	535

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

**ACTION NVESTIGATE** MONITOR **ITEM** YES NO **DESCRIPTION** SENT TO DSM **CREST** General Condition: Good / Fair / Poor Repairs: Date: Cracking Х Χ Settlement **Erosion Rills** Χ Χ **Animal Burrows** Χ Misalignment Vegetation (greater than 12") Χ **UPSTREAM EMBANKMENT** | General Condition: Good / Fair / Poor Repairs: Date: Cracking Χ Sloughing / Bulging Minor sloghing on south side-continuing to monitor Χ Seepage Χ Sink Holes Χ **Animal Burrows** Χ **Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") **DOWNSTREAM EMBANKMENT** General Condition: Good / Fair / Poor Repairs: Date: Cracking Χ Χ Sloughing / Bulging Χ Seepage Х Sink Holes Χ Sand Boils (indicate if flowing and color) Χ **Animal Burrows Erosion Rills** erosion on access roads to lake pump and west side of a lχ Vegetation (greater than 12") General Condition: Good / Fair / Poor SPILLWAY(S) Repairs: Date: Actively Flowing (provide depth) Χ Removed 1 stop log 11/16/22 Χ **Obstructions Present** Χ Seepage Χ Sand Boils (indicate if flowing and color) **Erosion Rills**