Dynegy CCR Joppa East Ash Pond Weekly Inspection Checksheet

Date	4-21-21
Inspector	REM
	77

Water level	Nucu. /
Temperature	53/
Weather	Clear

	ltem	Condition	Comments
Embankment	Vertical & Horizontal	C .	Comments
	Alignment of Crest	GC	
	Riprap	GC	
	Seepage	NE	
	Erosion	NE	
	Unusual Movement or		
	Cracking At or Beyond Toe	ME	
	Surface Cracks	GC	
	Sloughing or Erosion of Outer Embankment Slopes	NE	
	Sloughing or Erosion of Inner Embankment Slopes	NE	
	Animal Damage	NE	
	Vegetative Cover	Sc	
	Embankment Drainage Ditches	GC	·
Energy Dissipator (concrete box)	Riprap	GC	
	Outlet Channel	60	
	Concrete Condition	Carc	
	Debris	NE	
Decant Outfall Structur	Alignment	GC	
	Connection to Bollard	Gic	
	Debris in Inlets	MC	
		,	
		\.	

Condition Codes

- EC = Emergency Condition. A serious dam safety condition exists that needs immediate action. Report immediately to Chief Dam Safety Engineer and
- IM = Item needing immediate maintenance to restore or ensure its safety or integrity. Remediation should be completed within 1 month.
- MM = Item needing minor maintenance. The safety or integrity of the item is not yet Imperiled.
- OB = Condition requires regular observation to ensure that the condition does not become worse.
- GC = Good Condition.
- NE = No evidence of a problem.
- NI = Not Inspected. Reason should be stated in comment.