



iii) Since previous annual inspection:		Approximate Depth / Elevation					
		Elevation (ft)			Depth (ft)		
		Minimum	Present	Maximum	Minimum	Present	Maximum
Impounded Water			501			11	
CCR			508			45	
Discharge Invert		NA		NA	NA	NA	NA

iv) Storage capacity of the impounding structure at the time of the inspection (acre-ft): 1450

v) Approximate volume of the impounded water and CCR at the time of the inspection (acre-ft):

water volume: 150

CCR volume: 900

vi) Are there any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit and appurtenant structures?

None observed.

---



---



---

vii) Are there any other changes which may have affected the stability or operation of the impounding structure since the previous annual inspection?

The 12/01/2015 inspection was the first annual inspection completed in accordance with the above-cited regulations. Plant personnel report no such changes.

---



---



---

I, James Knutelski, P.E., am a duly Registered Professional Engineer under the laws of the state of Ohio. The information herein is to the best of my knowledge and belief, true, accurate and complete.

Dated: 1/18/2016



iii)	Since previous annual inspection:	Approximate Depth / Elevation					
		Elevation (ft)			Depth (ft)		
		Minimum	Present	Maximum	Minimum	Present	Maximum
	Impounded Water		499			24	
	CCR		490			25	
	Discharge Invert	NA		NA	NA	NA	NA

iv) Storage capacity of the impounding structure at the time of the inspection (acre-ft): 900

v) Approximate volume of the impounded water and CCR at the time of the inspection (acre-ft):

water volume: 450

CCR volume: 350

vi) Are there any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit and appurtenant structures?

None observed.

---



---



---

vii) Are there any other changes which may have affected the stability or operation of the impounding structure since the previous annual inspection?

The 12/01/2015 inspection was the first annual inspection completed in accordance with the

---

above-cited regulations. Plant personnel report no such changes.

---



---



---

I, James Knutelski, P.E., am a duly Registered Professional Engineer under the laws of the state of Ohio. The information herein is to the best of my knowledge and belief, true, accurate and complete.

Dated: 1/18/2016

# Miami Port

Basin B

Legend  
● Feature 1

P002

P001

Google earth

400 ft

