CCR Impoundment Weekly Inspection 35 ILL, ADM, Code 845 / 40 CER Part 257

~	33	ILL. A	NDIVI. Code 845 / 40 CFR Part 257					
Station: Jopp	Date:	Date: 3-2-22						
Impoundment Name: East	Time:	13:35						
IEPA Number: W127	01000	04-	02 Inspector(s):	R. Fair L.		r:		
25				- cong -		ŗ.	,	
Sky: Clear Temp.: 75%		_ F	Precip. (last 48 hrs):	Pool	Elev.: 4.74			
rect.							21.	
the time of inspection. If "ACTION" salested	n, extent	s, colo	or) and location in "DESCRIPTION" section. "NO" response	onse indicates no	issues	were o	bservec	
ditional sheets as necessary. Circle General C	Condition	offor e	TE", please indicate date forwarded via email to Dam :	Safety Manager	(DSM) .	Attack	1	
				-	,	ACTIO	NI	
ITEM								
		NO	DESCRIPTION		l %	GAT		
					MONITOR	NVESTIGATE	T T	
F 4 2				2	δ	<u> </u>	SENT TO DSM	
	ndition:	Good	Fair / Poor Repairs: Da	ate:				
Cracking		V						
Settlement	_	~				1	21.2	
Erosion Rills		V		1			1277	
Animal Burrows		V						
Misalignment		V						
egetation (greater than 12")	Garrens Circ	V						
TREAM EMBANKMENT General Co	ndition:	Good	Fair / Poor Repairs: Da	ate:	\$ 100 and 100	16 0 4 4 V		
Cracking		V					1	
Sloughing / Bulging		V						
Seepage	_	V						
Sink Holes		V				=		
Animal Burrows		V						
Erosion Rills		V					1. 1	
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")			Dead regetation at water line.					
OWNSTREAM EMBANKMENT General Co	ndition	-	/ Fair / Poor Repairs: Da	ate:				
Cracking						- 3-		
Sloughing / Bulging		V						
Seepage		V						
Sink Holes	_	V						
Sand Boils (indicate if flowing and color)		V						
Animal Burrows		V						
Erosion Rills								
Vegetation (greater than 12")	464000 ACC	7	Sa Nipla, the second of the San					
SPILLWAY(S) General Cor	ndition:	-		ate:				
Actively Flowing (provide depth)	V		5.5" unter flow at outfall struct	ve.			10.21	
ostructions Present								
Seepage		~				1 2		
Sand Boils (indicate if flowing and color)		~						

Erosion Rills