Geosyntec[▷]

consultants

		Residuals (CCR) Landfill Ins	pection Report
Site Name: Duck Creek Power Plant			
Site Address: 17751 North Cilco Road, Canton, IL 61520			
Owner/Operator: Illinois Power Resources Generating LLC			
Owner/Operator Address: 17751 North Cilco Road, Canton, IL 61520			
CCR Unit: CCR Landfill			
40 C.F.R. § 257.84 INSPECTION RE	OUIDEMENTS FOD CO	CD I ANDEII I S	
(b) ANNUAL INSPECTIONS BY			
			st be inspected on a periodic basis by a qualified
			ince of the CCR unit is consistent with recognized
		he inspection must, at a minimu	
(i) A review of available information regarding the status and condition of the CCR unit, including, but not limited to, files			
available in the operating record (e.g., the results of inspections by a qualified person, and results of previous annual			
inspections); and			
Qualified person inspect	ion documentation (weekly	inspection reports) and previou	is annual inspection reports were reviewed.
(ii) A visual inspection of the CCR unit to identify signs of distress or malfunction of the CCR unit.			
A visual inspection was performed by Zachary J. Fallert, P.E. on October 3, 2023. The inspection included the CCR landfill slopes			
and surface, stormwater	collection system, perimeter	er roads, and exterior slopes.	
(2) INSPECTION REPORT	. The qualified profession	al engineer must prepare a rep	port following each inspection that addresses the
following:			
		the previous annual inspection;	
Based on available plant records, the geometry was not changed since the previous annual inspection.			
(ii) The approximate volume of CCR contained in the unit at the time of the inspection;			
1,078,460 Cubic Yards	· · · · ·		
			nit, in addition to any existing conditions that are
		ration and safety of the CCR un	
			potential to disrupt operation of the landfill were ver slopes and covered landfill crest are vegetated.
Only minor erosion, sedimentation in a culvert ditchline, and vegetation taller than 12 inches were observed which are corrected through normal and regular maintenance.			
(iv) Any other change(s)	which may have affected	the stability or operation of the	CCR unit since the previous annual inspection.
Based on available plant	records and visual observ	ation, no changes were observe	d that are expected to impact stability or operation
of the CCR unit.			
I Zachary I Fallert being a Registered P	Professional Engineer in go	od standing in the State of Illing	bis, do hereby certify, to the best of my knowledge,
			as been prepared in accordance with the accepted
practice of engineering and the requireme			as seen prepared in accordance with the accepted
provide of engineering and the requirement			F
Zachary J. Fallert			
Printed Name			IN ROFESSION
			NO CAL
/			
2.10			S ZACHARY J.
VIV Y		11/13/2023	062-073263
Signature		Date	
6			
062-073263	IL	11/30/2023	GE2-073263
Registration Number	State	Expiration Date	in an
	Stute	2pituton Duto	