

CCR Impoundment Weekly Inspection
35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Duck Creek
 Impoundment Name: Ash Pond No. 1
 IEPA Number: W0578010001-01

Date: 10/11/23
 Time: 9:00 a.m.
 Inspector(s): Brandon Potter, Amy Johnson

Sky: Cloudy Temp.: 57° Precip. (last 48 hrs): 0" Pool Elev.: NA

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

| ITEM | YES | NO | DESCRIPTION | ACTION | | |
|--|--|-------------------------------------|----------------------------|---------|-------------|-------------|
| | | | | MONITOR | INVESTIGATE | SENT TO DSM |
| CREST | General Condition: <u>Good</u> / Fair / Poor | | Repairs: _____ Date: _____ | | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Settlement | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Misalignment | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| UPSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | Repairs: _____ Date: _____ | | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Slope Protection / Rip Rap | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| DOWNSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | Repairs: _____ Date: _____ | | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| SPILLWAY(S) | General Condition: <u>Good</u> / Fair / Poor | | Repairs: _____ Date: _____ | | | |
| Actively Flowing (provide depth) | | <input checked="" type="checkbox"/> | | | | |
| Obstructions Present | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |

CCR Impoundment Weekly Inspection
35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Duck Creek
 Impoundment Name: Ash Pond No. 2
 IEPA Number: W0578010001-02

Date: 10/11/23
 Time: 9:00 a.m.
 Inspector(s): Brandon Potter, Daryl Johnson

Sky: Cloudy Temp.: 57° Precip. (last 48 hrs): 0" Pool Elev.: NA

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

| ITEM | YES | NO | DESCRIPTION | ACTION | | |
|--|--|-------------------------------------|----------------------------|---------|-------------|-------------|
| | | | | MONITOR | INVESTIGATE | SENT TO DSM |
| CREST | General Condition: <u>Good</u> / Fair / Poor | | Repairs: _____ Date: _____ | | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Settlement | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Misalignment | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| UPSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | Repairs: _____ Date: _____ | | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Slope Protection / Rip Rap | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| DOWNSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | Repairs: _____ Date: _____ | | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| SPILLWAY(S) | General Condition: <u>Good</u> / Fair / Poor | | Repairs: _____ Date: _____ | | | |
| Actively Flowing (provide depth) | | <input checked="" type="checkbox"/> | | | | |
| Obstructions Present | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |

CCR Impoundment Weekly Inspection
35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Duck Creek
Impoundment Name: Bottom Ash Basin
IEPA Number: W0578010001-03

Date: 10/11/23
Time: 9:00 a.m.
Inspector(s): Brandon Potter; Daryl Johnson

Sky: Cloudy **Temp.:** 57° **Precip. (last 48 hrs):** 0" **Pool Elev.:** NA

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

| ITEM | YES | NO | DESCRIPTION | ACTION | | |
|--|--|-------------------------------------|-------------|----------------------------|-------------|-------------|
| | | | | MONITOR | INVESTIGATE | SENT TO DSM |
| CREST | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Settlement | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Misalignment | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| UPSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Slope Protection / Rip Rap | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| DOWNSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| SPILLWAY(S) | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Actively Flowing (provide depth) | | <input checked="" type="checkbox"/> | | | | |
| Obstructions Present | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |

CCR Impoundment Weekly Inspection
35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Duck Creek
Impoundment Name: GMF Pond
IEPA Number: W0578010001-04

Date: 10/11/23
Time: 9:00 a.m.
Inspector(s): Brandon Potter, Dargi Johnson

Sky: Cloudy **Temp.:** 57° **Precip. (last 48 hrs):** 0" **Pool Elev.:** NA

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

| ITEM | YES | NO | DESCRIPTION | ACTION | | |
|--|--|-------------------------------------|-------------|----------------------------|-------------|-------------|
| | | | | MONITOR | INVESTIGATE | SENT TO DSM |
| CREST | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Settlement | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Misalignment | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| UPSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Slope Protection / Rip Rap | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| DOWNSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| SPILLWAY(S) | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Actively Flowing (provide depth) | | <input checked="" type="checkbox"/> | | | | |
| Obstructions Present | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |

CCR Impoundment Weekly Inspection
35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Duck Creek
Impoundment Name: GMF Recycle Pond
IEPA Number: W0578010001-05

Date: 10/11/23
Time: 9:00 a.m.
Inspector(s): Brandon Potter; Daryl Johnson

Sky: Cloudy **Temp.:** 57°F **Precip. (last 48 hrs):** 0" **Pool Elev.:** NA

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

| ITEM | YES | NO | DESCRIPTION | ACTION | | |
|--|--|-------------------------------------|-------------|----------------------------|-------------|-------------|
| | | | | MONITOR | INVESTIGATE | SENT TO DSM |
| CREST | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Settlement | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Misalignment | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| UPSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Slope Protection / Rip Rap | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| DOWNSTREAM EMBANKMENT | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Cracking | | <input checked="" type="checkbox"/> | | | | |
| Sloughing / Bulging | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sink Holes | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Animal Burrows | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |
| Vegetation (greater than 12") | | <input checked="" type="checkbox"/> | | | | |
| SPILLWAY(S) | General Condition: <u>Good</u> / Fair / Poor | | | Repairs: _____ Date: _____ | | |
| Actively Flowing (provide depth) | | <input checked="" type="checkbox"/> | | | | |
| Obstructions Present | | <input checked="" type="checkbox"/> | | | | |
| Seepage | | <input checked="" type="checkbox"/> | | | | |
| Sand Boils (indicate if flowing and color) | | <input checked="" type="checkbox"/> | | | | |
| Erosion Rills | | <input checked="" type="checkbox"/> | | | | |