CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards	Date:	6-2-21
Impoundment Name:	Ash Pond	Time:	9:30 AM.
IEPA Number:	W1438050005-01	Inspector(s):	Rick Kelley

Sky: <u>Overcast</u> Temp.: <u>F70°F</u> Precip. (last 48 hrs): 0.07"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

Pool Elev.: 447.4

ACTION NVESTIGATE YES NO **ITEM** DESCRIPTION **AONITOR CREST** General Condition: Good PFair / Poor Repairs: Date: Cracking Settlement **Erosion Rills Animal Burrows** Misalignment Currently being mowed Vegetation (greater than 12") UPSTREAM EMBANKMENT | General Condition Good Fair / Poor Repairs: Date: Cracking Sloughing / Bulging Seepage Sink Holes **Animal Burrows Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") Currently being mowed DOWNSTREAM EMBANKMENT General Condition, Good / Pair / Poor Date: Cracking Sloughing / Bulging Seepage Sink Holes Sand Boils (indicate if flowing and color) X **Animal Burrows Erosion Rills** Currently being mowed today Vegetation (greater than 12") SPILLWAY(S) General Condition; Good Fair / Poor Repairs: Actively Flowing (provide depth) **Obstructions Present** X Seepage Sand Boils (indicate if flowing and color) **Erosion Rills**