CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards	Date: 8/25/2/
Impoundment Name:	Ash Pond	Time: 2:10 p.m.
IEPA Number:	W1438050005-01	Inspector(s): Rick Kelley

Sky: Partly Temp.: 90.1 °F Precip. (last 48 hrs): 0.22" Pool Elev.: 447.3

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

					ACTION			
ITEM	YE	S NO	DESCRIPTION		V	MONITOR	INVESTIGATE	SENT TO DSM
CREST G	eneral Conditio	n: 2600	Fair / Poor	Repairs:	Date:			
Cracking		1						
Settlement		V						
Erosion Rills								
Animal Burrows		V		-				
Misalignment		1						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT General Cond		1 G000	/ Fair / Poor	Repairs:	Date:			
Cracking								
Sloughing / Bulging		V						
Seepage								
Sink Holes		V						
Animal Burrows		V						
Erosion Rills		~						
Slope Protection / Rip Rap		V	,					
Vegetation (greater than 12")		1						
DOWNSTREAM EMBANKMENT G	eneral Conditio	Góod	Fair / Poor	Repairs:	Date:			
Cracking		X						
Sloughing / Bulging		X						
Seepage		X						
Sink Holes		X						
Sand Boils (indicate if flowing and color)		X						
Animal Burrows		X						
Erosion Rills		X						
Vegetation (greater than 12")		X						
SPILLWAY(S) Ge	eneral Condition	1:6000		Repairs:	Date:			
Actively Flowing (provide depth) <i>V</i>		R -1.5"					
Obstructions Present		X						
Seepage		X						
Sand Boils (indicate if flowing and color)		X						
Erosion Rills	147	X						