CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards		Date	12/15/21
Impoundment Name:	Ash Pond		Time	9.45 AM
IEPA Number:	W1438050005-	01	Inspector(s)	: Rick Kelley
Sky: Heavy Temp.:	62°F	Precip. (last 48 hrs):	0.01"	Pool Elev.: 447.4
"YES" responses require description at the time of inspection. If "ACTION additional sheets as necessary. Circle	I" selected is "INVEST	IGATE", please indicate date		esponse indicates no issues were observed am Safety Manager (DSM) . Attach
			•	ACTION

ITEM							ACTION		
		YES	NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condi	tion	Good	Fair / Poor	Repairs:	Date:			
Cracking			/						
Settlement									
Erosion Rills			V						
Animal Burrows									
Misalignment			V		***************************************				
Vegetation (greater than 12	!")								
UPSTREAM EMBANKMENT	General Condi	tion(Good	Fair / Poor	Repairs:	Date:			
Cracking			V						
Sloughing / Bulging									
Seepage									
Sink Holes			/						
Animal Burrows			1						
Erosion Rills			1	1500			Ī		
Slope Protection / Rip Rap			1						
Vegetation (greater than 12")			V						
DOWNSTREAM EMBANKMEN	T General Condi	tion	Good	Fair / Poor	Repairs:	Date:			
Cracking				~~~					
Sloughing / Bulging				NECESIA CO	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
Seepage									
Sink Holes				2015, 1011 15 3		3111			
Sand Boils (indicate if flowing and color)			/						
Animal Burrows				/					
Erosion Rills				41 10	(MINISTER AND	2			
Vegetation (greater than 12")									
SPILLWAY(S)	General Condi	tion	Goot	Fair / Poor	Repairs:	Date:		N. S.	
Actively Flowing (provide of	de la companya della companya della companya de la companya della			≈ 1.5	11				
Obstructions Present		V			high Beaver dam	@ river flager gate			
Seepage						11 3			\Box
Sand Boils (indicate if flowing	ng and color)								
Erosion Rills			V						