CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Edv	Station: Edwards		Date: 01/05/202	2			
Impoundment Name: Ash Pond			Time: 1430		ŧ.		
IEPA Number: W1438050005		-01	Inspector(s): Rick Kelle	4			
Sky: Partly Temp.: 13%				ol Elev.: 447.4			
	"INVES	TIGAT	r) and location in "DESCRIPTION" section. "NO" response indicates no E", please indicate date forwarded via email to Dam Safety Manager (ach section.				
					ACTION		
ITEM	YES	NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Cor	ndition	Good	Y Fair / Poor Repairs: Date:		MIT		
Cracking		V					
Settlement		V					
Erosion Rills							
Animal Burrows		V					
Misalignment		/	1000			1	
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT General Cor	dition	booE	DFair / Poor Repairs: Date:				
Cracking							
Sloughing / Bulging			- 178 ÷ 17				
Seepage							
Sink Holes							
Animal Burrows		/					
Erosion Rills		/				- 1	
Slope Protection / Rip Rap	1						
Vegetation (greater than 12")							
OOWNSTREAM EMBANKMENT General Con	dition;	3000	Fair / Poor Repairs: Date:	11-12		75	
Cracking							
Sloughing / Bulging		V					
Seepage		1					
Sink Holes		V					
Sand Boils (indicate if flowing and color)		V	***	\neg			
Animal Burrows		1		$\neg \neg$			
Erosion Rills		1	- 10.10%				
Vegetation (greater than 12")		1		\neg			
SPILLWAY(S) General Con	dition:	good	/ Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)	V		æ1.5*		-		
Obstructions Present			Beaver dam/brush - Currently under but				
Seepage		~	Beaver dam/brush - Currently under unta River Discharge Flapper Gate				
	_						

Sand Boils (indicate if flowing and color)

Erosion Rills