CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

		LL. A	DIVI. Code 845 / 40 CFR Part 25/			
Station: Edw Impoundment Name: Ash I W143805			Date: 3-9-20	22		
			Time: 1/: 15 A	N		
		-01	Inspector(s): Rick Kel	ley		
Sky: <u>Clear</u> Temp.:	39°F	P	Precip. (last 48 hrs): O.O * Pool	Elev.:	4	47.4
"YES" responses require description (size, of at the time of inspection. If "ACTION" selected additional sheets as necessary. Circle General	ted is "INVES	TIGAT	r) and location in "DESCRIPTION" section. "NO" response indicates no E", please indicate date forwarded via email to Dam Safety Manager (lach section.	issues (were ol Attach	oserved
				ACTION		
ITEM	YES	NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM
CREST Gener	al Condition	Good	/ Fair / Poor Repairs: Date:			
Cracking						
Settlement						
Erosion Rills						
Animal Burrows						
Misalignment		V				
Vegetation (greater than 12")						
UPSTREAM EMBANKMENT Gener	al Condition.	Good	/ Fair / Poor Repairs: Date:			
Cracking						
Sloughing / Bulging						
Seepage						
Sink Holes		V				
Animal Burrows		V,				
Erosion Rills						
Slope Protection / Rip Rap		V	Run aff line repailed			
Vegetation (greater than 12")		V				
DOWNSTREAM EMBANKMENT Gener	al Condition	Good	/ Fair / Poor Repairs: Date:			
Cracking						
Sloughing / Bulging						
Seepage						
Sink Holes		V				
Sand Boils (indicate if flowing and co	or)					
Animal Burrows		/				
Erosion Rills						
Vegetation (greater than 12")	55	1				
SPILLWAY(S) Gener	al Condition:	500d	/ Fair / Poor Repairs: Date:			
Actively Flowing (provide depth)			£ 1.5"			
Obstructions Present		V		\neg		

Sand Boils (indicate if flowing and color)

Erosion Rills