CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edward				Date: 5/4/2	2022		
Impoundment Name: Ash		d	_		Time: 2:45	PM		
IEPA Number:	W1438050005-01		•	Inspe	ctor(s): Rick	Kelley		
Sky: Cloudy Temp.:	60.2°F		Precip. (last 48 hrs):	0.37"	Pc	ool Elev.:	44	17.4
"YES" responses require description (s at the time of inspection. If "ACTION" additional sheets as necessary. Circle	selected is "INV	'ESTIGA	TE", please indicate date	CRIPTION" section. e forwarded via em	"NO" response indicates ail to Dam Safety Manag	no issues v	vere o	bserved
ITEM			DESCRIPTION			P	ACTIO	
		SNC				MONITOR	INVESTIGATE	SENT TO DSM
CREST	eneral Conditio	n: 600	/ Fair / Poor	Repairs:	Date:			
Cracking		V						
Settlement		V						
Erosion Rills		V	1					
Animal Burrows		V	1					
Misalignment		V						
Vegetation (greater than 12")	V		Need to s	chedule me	wing	V		
UPSTREAM EMBANKMENT G	eneral Conditio	n: G001	/ Fair / Poor	Repairs:	Date:			
Cracking		L	1					
Sloughing / Bulging		L	1					
Seepage		V						
Sink Holes		1					-	
Animal Burrows		V		1				1
Erosion Rills		V						
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		1	1				П	
DOWNSTREAM EMBANKMENT G	eneral Condition	1: 6000	Fair / Poor	Repairs:	Date:			QUE!
Cracking		1	ł					
Sloughing / Bulging		V				+		
Seepage		V	1			_		
Sink Holes		V						
Sand Boils (indicate if flowing an	d color)	1				+		
Animal Burrows								
Erosion Rills		V						\vdash
Vegetation (greater than 12")	/		Need to	schedule n	nouida			
	eneral Condition	1: 6000	Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth			2 1.0-1		55.5.			
Obstructions Present		1	70 110 11.			+ +		
Seepage		1				+ +		

Sand Boils (indicate if flowing and color)

Erosion Rills