CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards		Date: 5/19	3/2022	,		
Impoundment Name:	Ash Pond W1438050005-01		Time: /3.	BO			
				K Kelley	- 3		
Sky: <u>Cloudy</u> Temp.:	71.4°F	P	recip. (last 48 hrs): 0.3	Pool Elev.:	44	7.4	
"YES" responses require description (at the time of inspection. If "ACTION additional sheets as necessary. Circle	" selected is "INVES	TIGAT	r) and location in "DESCRIPTION" section. "NO" response indicates, please indicate date forwarded via email to Dam Safety March section.	ates no issues inager (DSM)	were o	bserved	
					ACTION		
ITEM		NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Condition:	Good	Y Fair / Poor Repairs: Date:			Van d	
Cracking							
Settlement			,				
Erosion Rills							
Animal Burrows						\vdash	
Misalignment							
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT	General Condition	Good	Fair / Poor Repairs: Date:		*PAGED	173.00	
Cracking							
Sloughing / Bulging		V					
Seepage		1					
Sink Holes		V					
Animal Burrows							
Erosion Rills		1					
Slope Protection / Rip Rap							
Vegetation (greater than 12")							
DOWNSTREAM EMBANKMENT	General Condition:	5000	Fair / Poor Repairs: Date:	MINI ENS		W. Sala	
Cracking		V					
Sloughing / Bulging							
Seepage							
Sink Holes		/					
Sand Boils (indicate if flowing and color)							
Animal Burrows		V					
Erosion Rills		1	/				
Vegetation (greater than 12")		V					
SPILLWAY(S)	General Condition: (5000	Fair / Poor Repairs: Date:				
Actively Flowing (provide dep	th)		×1.0-1.5"				
Obstructions Present		V					

Seepage

Erosion Rills

Sand Boils (indicate if flowing and color)