CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Edwards Date: 5/25/2023
Impoundment Name: Ash Pond Time: 1400
IEPA Number: W1438050005-01 Inspector(s): Rick Kelley

Sky: Cloudy

Temp.: 74.8°F

Precip. (last 48 hrs):

0.03"

Pool Elev.: <u>447. 4</u>

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

						ACTION		
ITEM		NO	DESCRIPTION			MONITOR	INVESTIGATE	SENT TO DSM
CREST Gene	eral Condition.	Good	Fair / Poor	Repairs:	Date:	AT		
Cracking		V						
Settlement		V						
Erosion Rills								
Animal Burrows								
Misalignment			/	,				
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT Gene	eral Condition	Good	Fair / Poor	Repairs:	Date:			
Cracking		V	8					
Sloughing / Bulging								
Seepage		V	,					
Sink Holes				<u></u>	· · · · · · · · · · · · · · · · · · ·			
Animal Burrows								
Erosion Rills				-				
Slope Protection / Rip Rap		V	/					
Vegetation (greater than 12")		V						
DOWNSTREAM EMBANKMENT Gene	eral Condition:	6000	/ Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging								
Seepage								
Sink Holes								
Sand Boils (indicate if flowing and c	olor)							
Animal Burrows								
Erosion Rills			/					
Vegetation (greater than 12")		~						
	ral Condition	Good	Fair / Poor	Repairs:	Date:	, ab		155
Actively Flowing (provide depth)			R 1.5	//	*		- Sales	
Obstructions Present								
Seepage								$\vdash \vdash$
Sand Boils (indicate if flowing and co	olor)							
Erosion Rills					·			-