CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards	Date:	6/1/2022
Impoundment Name:	Ash Pond	Time:	12:00 pm
IEPA Number:	W1438050005-01	Inspector(s):	Rick Kelley

Sky: <u>Cloudy</u> Temp.: <u>69°F</u> Precip. (last 48 hrs): <u>0.55</u>" Pool Elev.: <u>447.2</u>

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as necessary.								ACTION		
ITEM		YES	NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Condit	ion: (Good Fair / Poo	r	Repairs:	Date:				
Cracking			V							
Settlement										
Erosion Rills										
Animal Burrows			V							
Misalignment				11-33						
Vegetation (greater than 12")										
UPSTREAM EMBANKM	NT General Condit	iop	Good DFair / Poo	r	Repairs:	Date:				
Cracking						-500				
Sloughing / Bulging										
Seepage				*22						
Sink Holes			/							
Animal Burrows										
Erosion Rills			/							
Slope Protection / Rip Rap										
Vegetation (greater than	n 12")		/							
DOWNSTREAM EMBANKW	IENT General Condit	ion.	Good / Fair / Poo	r	Repairs:	Date:				
Cracking	•		V							
Sloughing / Bulging										
Seepage										
Sink Holes										
Sand Boils (indicate if flowing and color)										
Animal Burrows			V	200	# II					
Erosion Rills							1			
Vegetation (greater than	n 12")		/				100			
SPILLWAY(S)	General Condit	ion.	Good Dair / Poo	r	Repairs:	Date:				
Actively Flowing (provi	de depth)	V	2	/ "						
Obstructions Present			V							
Seepage			/	N# 117						
Sand Boils (indicate if flowing and color)			V							
Erosion Rills										