## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Edwards
Impoundment Name: Ash Pond
IEPA Number: W1438050005-01

Date: 6/15/2022
Inspector(s): Rick Kelley

Sky: <u>Clear</u> Temp.: <u>87.8 F</u> Precip. (last 48 hrs): <u>0.0"</u> Pool Elev.: <u>447.4</u>°

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM								ACTION		
		YES	NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Cond	lition:	Good	Fair / Poor	Repairs:	Date:				
Cracking			V							
Settlement										
Erosion Rills										
Animal Burrows			V		ATTIXALE.					
Misalignment										
Vegetation (greater than 12")			V							
UPSTREAM EMBANKM	ENT General Cond	ition	Good	/ Fair / Poor	Repairs:	Date:				
Cracking										
Sloughing / Bulging				,						
Seepage				***						
Sink Holes			V							
Animal Burrows										
Erosion Rills			V							
Slope Protection / Rip Rap										
Vegetation (greater than 12")			1							
DOWNSTREAM EMBANKW	<b>1ENT</b> General Cond	ition:(	Good	Fair / Poor	Repairs:	Date:				
Cracking										
Sloughing / Bulging										
Seepage			V				1.5-			
Sink Holes										
Sand Boils (indicate if flowing and color)				•						
Animal Burrows			/							
Erosion Rills				(a = 25 to 10 to 10 to		mes.				
Vegetation (greater than 12")										
SPILLWAY(S)	General Cond	ition	Good	Fair / Poor	Repairs:	Date:		N A		
Actively Flowing (provi		V		R 1.5		1 1 9 1 1 1 1				
Obstructions Present			~							
Seepage			V							
Sand Boils (indicate if flowing and color)			V							
Erosion Rills			V	5 (80)222 3	3.50 3.50 3.50					