CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Edwards Date: 6/22/22
Impoundment Name: Ash Pond Time: 13:00
IEPA Number: W1438050005-01
Inspector(s): Rick Kelley

Sky: Partly Temp.: 85.8 F Precip. (last 48 hrs): 0.0 Pool Elev.: 447.4

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION		
					MONITOR	INVESTIGATE	SENT TO DSM
CREST General Cor	dition	Good	Fair / Poor Repairs:	Date:			
Cracking			,				
Settlement							
Erosion Rills							
Animal Burrows		V			-		
Misalignment							
Vegetation (greater than 12")				33330			
UPSTREAM EMBANKMENT General Cor	dition	Good	Fair / Poor Repairs:	Date:			
Cracking							
Sloughing / Bulging			- Maria				
Seepage		/					
Sink Holes							
Animal Burrows		1					
Erosion Rills							
Slope Protection / Rip Rap				27.0			
Vegetation (greater than 12")							
DOWNSTREAM EMBANKMENT General Cor	dition	Good	Fair / Poor Repairs:	Date:			
Cracking		K	10000				
Sloughing / Bulging				5. 1 HES H. 138			
Seepage		/					
Sink Holes		V					
Sand Boils (indicate if flowing and color)							
Animal Burrows		~	11 1000	ANTENDO			
Erosion Rills							
Vegetation (greater than 12")							
SPILLWAY(S) General Cor	dition:	Good		Date:			
Actively Flowing (provide depth)	V.		K 1.0-15"				
Obstructions Present		~	•				
Seepage			ž aud-				
Sand Boils (indicate if flowing and color)							
Erosion Rills							