CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Edwards	Date:	6/29/02
Ash Pond	Time:	11:00 A.M.
W1438050005-01	Inspector(s):	Rich Kellen
	Ash Pond	Ash Pond Time:

Sky: <u>Clear</u> Temp.: <u>83°F</u> Precip. (last 48 hrs): <u>0.0</u>" Pool Elev.: <u>447.4</u>"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM				DESCRIPTION			_ A	ACTION			
		YES	NO				MONITOR	INVESTIGATE	SENT TO DSM		
CREST	General Condit	dition Soc		Dair / Poor	Repairs:	Date:					
Cracking											
Settlement			/						, i		
Erosion Rills											
Animal Burrows											
Misalignment					4						
Vegetation (greater than 12")											
UPSTREAM EMBANKMENT	General Condit	tion	good	Fair / Poor	Repairs:	Date:					
Cracking			1								
Sloughing / Bulging											
Seepage			V								
Sink Holes			1								
Animal Burrows											
Erosion Rills											
Slope Protection / Rip Rap			V,								
Vegetation (greater than 12")											
DOWNSTREAM EMBANKMENT	General Condit	tion	Good	/ Fair / Poor	Repairs:	Date:					
Cracking									,		
Sloughing / Bulging			V		72						
Seepage			-								
Sink Holes			V								
Sand Boils (indicate if flowing	and color)										
Animal Burrows			1								
Erosion Rills			1/								
Vegetation (greater than 12")			1								
SPILLWAY(S)	General Condit	tion	Good	/ Fair / Poor	Repairs:	Date:					
Actively Flowing (provide de	pth)	L	-	21.5"	***************************************						
Obstructions Present											
Seepage			V								
Sand Boils (indicate if flowing	and color)		1								
Erosion Rills			V								