CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Edwards Impoundment Name: Ash Pond Inspector(s): Rick Kelley IEPA Number: W1438050005-01 Temp.: 80°F Precip. (last 48 hrs): 0.04" "YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section. **ACTION NVESTIGATE ITEM** YES NO **DESCRIPTION** MONITOR SENT 1 **CREST** General Condition; Good Fair / Poor Repairs: Date: Cracking Settlement **Erosion Rills Animal Burrows** Misalignment Vegetation (greater than 12") UPSTREAM EMBANKMENT | General Condition: Good Fair / Poor Repairs: Date: Cracking Sloughing / Bulging Seepage Sink Holes **Animal Burrows Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") DOWNSTREAM EMBANKMENT | General Condition; Good/ Fair / Poor Repairs: Date: Cracking Sloughing / Bulging Seepage Sink Holes Sand Boils (indicate if flowing and color) **Animal Burrows Erosion Rills** Vegetation (greater than 12") SPILLWAY(S) General Condition; Good / Fair / Poor Repairs: Date: Actively Flowing (provide depth) **Obstructions Present**

Seepage

Erosion Rills

Sand Boils (indicate if flowing and color)