CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Edwards

Impoundment Name: Ash Pond

IEPA Number: W1438050005-01

Date: 7/20/22

Time: 1:45 pm

Inspector(s): Rick Kelley

Sky: <u>Cleur</u> Temp.: <u>87</u> Precip. (last 48 hrs): <u>0.0</u> Pool Elev.: <u>447.4</u>

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

							ACTIO	N
ITEM		NO	DESCRIPTION			MONITOR	INVESTIGATE	SENT TO DSM
CREST General Con	dition	Good	DFair / Poor	Repairs:	Date:			
Cracking								
Settlement				2				
Erosion Rills								
Animal Burrows								
Misalignment								
Vegetation (greater than 12")					A CONTRACTOR			
UPSTREAM EMBANKMENT General Con	dition.	Good	Fair / Poor	Repairs:	Date:			
Cracking				413 - 415				
Sloughing / Bulging								
Seepage			901					
Sink Holes								
Animal Burrows			A.C.		17.5			
Erosion Rills								
Slope Protection / Rip Rap		V	/					
Vegetation (greater than 12")				,				
DOWNSTREAM EMBANKMENT General Con	dition	Good	Fair / Poor	Repairs:	Date:			
Cracking		-				2.57		
Sloughing / Bulging		/						
Seepage								
Sink Holes			l East					
Sand Boils (indicate if flowing and color)		/						
Animal Burrows		/		2011-2010-2011-00	÷ //			
Erosion Rills								
Vegetation (greater than 12")		V		11904				
SPILLWAY(S) General Con	dition	Good		Repairs:	Date:			
Actively Flowing (provide depth)	/		/F 1.0	-1.5"				
Obstructions Present		/						
Seepage								
Sand Boils (indicate if flowing and color)								
Erosion Rills								