CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards	Date:	8/10/2022
Impoundment Name:	Ash Pond	Time:	9:45 AM
IEPA Number:	W1438050005-01	Inspector(s):	Rick Kelley
		-	

Temp.: 77°F Precip. (last 48 hrs):

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM						ACTION			
		NO	DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM		
CREST Ge	neral Condition	Good	Fair / Poor	Repairs: Date:					
Cracking		V							
Settlement									
Erosion Rills		1							
Animal Burrows		1							
Misalignment			Į.	STATE OF THE STATE					
Vegetation (greater than 12")									
UPSTREAM EMBANKMENT Ge	neral Condition	Good	Fair / Poor	Repairs:	Date:				
Cracking									
Sloughing / Bulging		V			127				
Seepage				3011. 311331					
Sink Holes		/							
Animal Burrows				PARACOLUM	10000				
Erosion Rills		\ <u>\</u>	/						
Slope Protection / Rip Rap		1							
Vegetation (greater than 12")		/							
DOWNSTREAM EMBANKMENT Ge	neral Condition	Good	Fair / Poor	Repairs:	Date:				
Cracking		V							
Sloughing / Bulging		/	,						
Seepage		1							
Sink Holes		/							
Sand Boils (indicate if flowing and color)									
Animal Burrows									
Erosion Rills				***					
Vegetation (greater than 12")			Noed to	Schedule mow	ing possible wood	V			
SPILLWAY(S) Ger	neral Condition	Good			Date:		Q - III		
Actively Flowing (provide depth)	V		F1.0-	1.5"					
Obstructions Present		/							
Seepage		V	32						
Sand Boils (indicate if flowing and color)				Paris and the second se					
Erosion Rills									