CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Edwards Date: 8/31/2022
Impoundment Name: Ash Pond Time: 10:30 AM
IEPA Number: W1438050005-01 Inspector(s): Rick Kellay

Sky: Clear Temp.: 78°F Precip. (last 48 hrs): 0.01" Pool Elev.: 447.4

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sneets as necessary. Circle 6		NO	DESCRIPTION		ACTION		
ITEM	YES				INVESTIGATE	SENT TO	
CREST Ge	eneral Condition	Good	Fair / Poor Repairs: Date:				
Cracking		1					
Settlement		V					
Erosion Rills		/		= 0			
Animal Burrows		/					
Misalignment		V					
Vegetation (greater than 12")			Needs moved	V			
UPSTREAM EMBANKMENT G	eneral Condition:	Good	Fair / Poor Repairs: Date:				
Cracking		~					
Sloughing / Bulging		1					
Seepage							
Sink Holes		1					
Animal Burrows		1					
Erosion Rills		1					
Slope Protection / Rip Rap		1					
Vegetation (greater than 12")			Needs mowed				
DOWNSTREAM EMBANKMENT G	eneral Condition	Good					
Cracking		V					
Sloughing / Bulging		V					
Seepage							
Sink Holes		1					
Sand Boils (indicate if flowing an	d color)	1					
Animal Burrows							
Erosion Rills							
Vegetation (greater than 12")			Needs mowed.				
SPILLWAY(S) Ge	eneral Condition	Good	Fair / Poor Repairs: Date:				
Actively Flowing (provide depth	1)		≈ 1.5"				
Obstructions Present		1					
Seepage							
Sand Boils (indicate if flowing and color)		1					
Erosion Rills		V					