## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards	Date: 9/7/22	
Impoundment Name:	Ash Pond	Time: 09:30 Am	,
IEPA Number:	W1438050005-01	Inspector(s): Rick Kelle	4

Sky: Part/2 Temp.: 72°F Precip. (last 48 hrs): 0.0" Pool Elev.: 447.4"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION			
					MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Con	dition:	Good	Fair / Poor Repairs: Date:				752	
Cracking		V						
Settlement								
Erosion Rills								
Animal Burrows								
Misalignment			/					
Vegetation (greater than 12")		V	Area mowed 9/2/22					
UPSTREAM EMBANKMENT General Con	dition	Good			H			
Cracking								
Sloughing / Bulging								
Seepage								
Sink Holes								
Animal Burrows								
Erosion Rills		V	•					
Slope Protection / Rip Rap			/					
Vegetation (greater than 12")			Area mowed 9/a/22					
DOWNSTREAM EMBANKMENT General Con	dition	Good	Fair / Poor Repairs: Date:					
Cracking				200				
Sloughing / Bulging		~						
Seepage			***************************************					
Sink Holes		1						
Sand Boils (indicate if flowing and color)								
Animal Burrows								
Erosion Rills		1						
Vegetation (greater than 12")		/	Area mowed 9/3/22					
SPILLWAY(S) General Con	dition	Good	Fair / Poor Repairs: Date:					
Actively Flowing (provide depth)	1		£ 1.0-15"					
Obstructions Present								
Seepage						_		
Sand Boils (indicate if flowing and color)		1						
Erosion Rills								

No issued noted with perimeter fencing. All access locations normal.