CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| | 22.1 | LL. M | Divi. Code 645 / 4 | U CFR Part 257 | | / | | | |
|--|-----------------------|--------|-------------------------|--------------------|---------------------------------------|-----------|-------------|--|--|
| Station: | Edwards | | | | Date: 10/19/ | 22 | | | |
| Impoundment Name: Ash Pond | | | | | Time: 12:30 | PM | • | | |
| IEPA Number: W1438050005 | | | | Inspe | ctor(s): Rickk | eleu | , | | |
| Sky: Partle Temp.: | 45°F | P | recip. (last 48 hrs): | 0.0" | Poo | ol Elev.: | 44 | 7.3 | |
| YES" responses require description | (size, depth, extents | , colo | r) and location in "DES | CRIPTION" section. | "NO" response indicates r | no issues | were o | bserved | |
| t the time of inspection. If "ACTION | I" selected is "INVES | TIGAT | E", please indicate da | | | | | | |
| dditional sheets as necessary. Circle | e General Condition | for ea | ich section. | | | | | | |
| | | | | | | - | ACTION | | |
| ITEM | YES | NO | | DESCRIPTIO | N | MONITOR | INVESTIGATE | SENT TO DSM | |
| CREST | General Condition | Good | Fair / Poor | Repairs: | Date: | | | | |
| Cracking | | V | | | | | | | |
| Settlement | | V | , | | | | | | |
| Erosion Rills | | | / | | _ | | | | |
| Animal Burrows | | V | | | | | | | |
| Misalignment | | V | | | | | | | |
| Vegetation (greater than 12") | | V | | | | | | | |
| UPSTREAM EMBANKMENT | General Condition | Good | Dair / Poor | Repairs: | Date: | | | | |
| Cracking | | V | 1.3000 | | | | | | |
| Sloughing / Bulging | | V | | | | | | | |
| Seepage | | V | | | | | | | |
| Sink Holes | | / | | | | | | | |
| Animal Burrows | | 1 | | | | | | | |
| Erosion Rills | | V | | 5970.4070 | | | | | |
| Slope Protection / Rip Rap | | V | | | | | <u> </u> | | |
| Vegetation (greater than 12") | | V | C-1411 | | | | | \square | |
| DOWNSTREAM EMBANKMENT | General Condition | Sood | / Fair / Poor | Repairs: | Date: | | | | |
| Cracking | | ~ | | | | | | | |
| Sloughing / Bulging | | _ | | | | | | \sqcup | |
| Seepage | | 1 | | | | | | | |
| Sink Holes | | / | | | | | | | |
| Sand Boils (indicate if flowing a | and color) | V | | | · · · · · · · · · · · · · · · · · · · | | | \sqcup | |
| Animal Burrows | | V | | | | | | | |
| Erosion Rills | | V | | | | | | | |
| Vegetation (greater than 12") | C 10 111 6 | V | \ | 1 | | | | | |
| | General Condition: | Good | | Repairs: | Date: | | | | |
| Actively Flowing (provide dep | otn) | | £ 1.0" | | | | | $\vdash \vdash \vdash$ | |
| Obstructions Present | | _ | / | | | | | | |
| Seepage | and sale \ | V | <u> </u> | | | + | | \vdash | |
| Sand Boils (indicate if flowing a Erosion Rills | and color) | - | | | | | | | |
| PERIMTER FENCING/GATES | Conoral Candities of | | Dinis / Dans | Inamaina | 0-1 | | | | |
| Evidence of damage or tan | | 3000 | Pair / Poor | Repairs: | Date: | | | | |
| Evidence of damage of lan | ibernik | V | 4 | | | 1 1 | , , | 1 1 | |

Evidence of unauthorized access

Gates closed and locked