## **CCR Impoundment Weekly Inspection**

35 ILL. ADM. Code 845 / 40 CFR Part 257 Station: Edwards Impoundment Name: **Ash Pond** IEPA Number: W1438050005-01 Temp.: 49 F Precip. (last 48 hrs): 0.0 " Pool Elev.: 447.3 "YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section. **ACTION NVESTIGATE ITEM** YES NO DESCRIPTION MONITOR SENT DSM **CREST** General Condition: Good / Fair / Poor Repairs: Date: Cracking Settlement V **Erosion Rills Animal Burrows** Misalignment Vegetation (greater than 12") UPSTREAM EMBANKMENT | General Condition: 600d / Fair / Poor Repairs: Date: Cracking Sloughing / Bulging 1 Seepage Sink Holes **Animal Burrows Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") DOWNSTREAM EMBANKMENT General Condition: Good / Fair / Poor Repairs: Date: Cracking Sloughing / Bulging Seepage V Sink Holes Sand Boils (indicate if flowing and color) **Animal Burrows Erosion Rills** Vegetation (greater than 12") SPILLWAY(S) General Condition: Good Fair / Poor Repairs: Date: Actively Flowing (provide depth) **Obstructions Present** Seepage Sand Boils (indicate if flowing and color) V **Erosion Rills** 

Repairs:

Date:

PERIMTER FENCING/GATES | General Condition: Good/ Fair / Poor

Evidence of damage or tampering Evidence of unauthorized access

Gates closed and locked