			ooundment Weekl OM. Code 845 / 40	•				
Chattan		.L. AL	NVI. Coue 645 / 40		,			
Station:	Edwards Ash Pond							
Impoundment Name: Ash P IEPA Number: W143805		Olid College			<u> </u>			
IEPA Number: _	W1438050005-0			inspector(s	I. I. Jayr	2	il.	
Sky: Cldy Temp.:	45°	1	recip. (last 48 hrs):	.oy"		l Elev.:		
YES" responses require description (si t the time of inspection. If "ACTION" dditional sheets as necessary. Circle	selected is "INVES	TIGAT	E", please indicate dat	CRIPTION" section. "NO" e forwarded via email to	response indicates Dam Safety Manage	r (DSM) .	Attacl	h
						ACTION		
ITEM	YES	NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM
CREST	ieneral Condition	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		~						
Settlement		u						
Erosion Rills		V		9	1			
Animal Burrows		~						
Misalignment		~						
Vegetation (greater than 12")		K						
UPSTREAM EMBANKMENT	Seneral Condition	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging		V						
Seepage	TI .	~					<u> </u>	
Sink Holes		4						
Animal Burrows		انا					<u> </u>	
Erosion Rills		V						
Slope Protection / Rip Rap								
Vegetation (greater than 12")	701	14						
DOWNSTREAM EMBANKMENT	General Condition:	6000	/ Fair / Poor	Repairs:	Date:			
Cracking	2	V						
Sloughing / Bulging		1				I		
Seepage		V						
Sink Holes		_			7001			
Sand Boils (indicate if flowing and color)							1	
Animal Burrows								
Erosion Rills		-		,				
Vegetation (greater than 12")		_				1		
	General Condition	:G000	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide dep	oth)	1	~ 1/2" wer	- 1/3 of the	discharge			
Obstructions Present		1			0			

Repairs:

Date:

Seepage

Erosion Rills

Sand Boils (indicate if flowing and color)

Evidence of damage or tampering Evidence of unauthorized access

Gates closed and locked

PERIMTER FENCING/GATES General Condition Good Fair / Poor