CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| | | 35 II | LL. A | OM. Code 845 / 4 | 10 CFR Part 257 | | | | | | | |
|--|--------------------------------------|-------------|------------------------|-----------------------|-----------------------|---------------------------------------|--------------|---------|-------------|----------------|--|--|
| Station: | Edwa | rds | | | | Date: <u>5</u> - | 3-23 | | | | | |
| Impoundment Name: Ash Po | | | d | | | Time: | | | | | | |
| IEPA Number: | W143805 | 0005 | -01 | | Inspect | or(s): <u>M</u> . | Dayis | | | | | |
| _ | ,,, 0 | | | | ^' | | D11 | -la | 1121 | 191 | | |
| Sky: Sun Temp.: | 46 | | Precip. (last 48 hrs): | | | | Pool Elev.: | | | 434.0 | | |
| /ES" responses require description | /size denth s | utonto | color |) and location in "DE | SCRIPTION" section " | 'NO" response | indicates no | issues | were o | hserve | | |
| t the time of inspection. If "ACTION | (size, depth, e: 1" selected is " | INVES | TIGAT | E", please indicate d | ate forwarded via ema | il to Dam Safet | y Manager (| DSM). | Attach |) | | |
| dditional sheets as necessary. Circl | | | | | | | | 1001 | | | | |
| | | | | | | | | | ACTION | | | |
| ITEM | | YES | NO | DESCRIPTION | | | | MONITOR | INVESTIGATE | SENT TO DSM | | |
| CREST | General Cond | lition; | 5000 | / Fair / Poor | Repairs: | Date: | | | | | | |
| Cracking | | | V | | | | | | | | | |
| Settlement | | | L | | | | | | | | | |
| Erosion Rills | | | ~ | | | | | | | | | |
| Animal Burrows | | | | | | | | | | | | |
| Misalignment | | | - | | | | | | | | | |
| Vegetation (greater than 12") | | | ~ | | | | | | | | | |
| | General Cond | lition: | Good | / Fair / Poor | Repairs: | Date: | | | | | | |
| Cracking | | | / | | | | | | | | | |
| Sloughing / Bulging | | | | | | | | | | | | |
| Seepage | | | | | , | | | | | | | |
| Sink Holes | | g. | - | | | | | | | | | |
| Animal Burrows | | | - | | | | | | | | | |
| Erosion Rills | | | - | | | | | | | | | |
| Slope Protection / Rip Rap | | | - | Weed spra | vina conduct | ted toda | V | | | | | |
| Vegetation (greater than 12") | | _ | | | 7.3 | 1 000 | 7 | | | | | |
| DOWNSTREAM EMBANKMENT | - | dition | Good | / Fair / Poor | Repairs: | Date: | | | | | | |
| Cracking | | | V | | | | | | | | | |
| Sloughing / Bulging | | | 1 | | | | | | | | | |
| Seepage | | | - | | | | | | | | | |
| Sink Holes | | | - | | | | | | | | | |
| Sand Boils (indicate if flowing | and color) | | 1 | | | | | | | | | |
| Animal Burrows | | | | | | | | | | | | |
| Erosion Rills | | | - | | | | | | , | | | |
| Vegetation (greater than 12" |) | 1 | L | Wedd Spra | ying around | Pond per | meter | n 5 | 12 8 | 5/3 | | |
| SPILLWAY(S) | General Cond | dition | | | Repairs: | Date: | TATE IS V | | | G (C) | | |
| Actively Flowing (provide de | | | 1 | No Disch | | A- | | | | | | |
| Obstructions Present | | _ | V | 140 5 301 | 2 | | | | | | | |
| Seepage | | V | - | Small street | om of Licker | lenkine | thron | uch | | | | |
| Sand Boils (indicate if flowing and color) | | 1 | 1 | Dischar | -· - | 10 1 | | twn | | | | |
| Erosion Rills | , 2114 201017 | | 1 | | J spr sall | · PICAN | <u> </u> | | | | | |
| PERIMTER FENCING/GATES | General Con- | dition | - Good | Pair / Poor | Repairs: | Date: | | | NE I | | | |
| | | 1 | | | | | | | | | | |
| Evidence of damage or tampering | | - | V | | | · · · · · · · · · · · · · · · · · · · | | | | | | |
| Evidence of unauthorized access | | | | | | | | | | + | | |

Gates closed and locked