CCK Impounament Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edward	S		- market to be the best of the second	Date: 7-5-3	72			
Impoundment Name:	Ash Pond W1438050005-01		ari in marcipali.	Time:					
IEPA Number:			Inspector(s): M. Davis						
Sky: Clear Temp.:	80°		Precip. (last 48 hrs):	0"	Po	ol Elev.	. 43	35.2	
/ES" responses require description	(size, depth, exter	its. colo	r) and location in "DES	CRIPTION" section "	NO" response indicates	no lecuat			
t the time of inspection. If "ACTION dditional sheets as necessary. Circl	N" selected is "INV	ESTIGAT	TE", please indicate dat	e forwarded via ema	il to Dam Safety Manage	r (DSM)	. Attach	1	
			Jen Jection.				ACTION		
ITEM	YE	S NO		DESCRIPTION		MONITOR	NVESTIGATE	SENT TO BSM	
CREST	General Conditio	n Good	VFair / Poor	Repairs:	Date:			IND	
Cracking		1							
Settlement		1					+		
Erosion Rills		1.					-		
Animal Burrows		1					-		
Misalignment		1./				-			
Vegetation (greater than 12")									
UPSTREAM EMBANKMENT		nigood	Pair / Poor	Repairs:	Date:	31.00			
Cracking	Solicial deligities	1	1411 / 1 001	Inchairs.	Date.			COLEGE	
Sloughing / Bulging		1							
Seepage		-				-	┼		
Sink Holes		1				-	├	ļ	
Animal Burrows		~							
Erosion Rills		1						-	
Slope Protection / Rip Rap							 		
Vegetation (greater than 12")	C		Some tragm	ytes grown	g near water	Sede	e_		
OWNSTREAM EMBANKMENT	General Condition	1: 600d	/Fair / Poor	Repairs:	Date:	-			
Cracking Sloughing / Bulging									
		-							
Seepage Sink Holes	3	V							
		-							
Sand Boils (indicate if flowing a Animal Burrows	and color)								
Erosion Rills									
Vegetation (greater than 12")			()						
The second section is a second section of the second section of the second section is a second section of the second section of the second section sec	General Condition	1: 6 00d		Repairs:	Date:				
Actively Flowing (provide depth)		V		manually - water leve		on	15"		
Obstructions Present		1	belo	w discha	uge spillwa	e pi	pe		
Seepage		1			U	9			
Sand Boils (indicate if flowing a	and color)								
Erosion Rills		K		1					
ERIMTER FENCING/GATES	the second second second	1: 2606	/ Fair / Poor	Repairs:	Date:				
Evidence of damage or tan	-								
Evidence of unauthorized a	access	V							

Gates closed and locked