## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station	Edwar	ds	Date: 8-30-23 Time: 1/30							
Impoundment Name:										
IEPA Number	W1438050	005-0	Maria Santa Cara Cara Cara Cara Cara Cara Cara Ca	Inspecto	or(s):	nvis		Remote .	CAN TO ST	
Sky: Clear Temp.	75°	Editor.	Precip. (last 48 hrs):	.50"		Pool E	lev.:	42	0.3	
YES" responses require description t the time of inspection. If "ACTIOI dditional sheets as necessary. Circ	N" selected is "IN	IVESTIG	ATE", please indicate da	CRIPTION" section: "N te forwarded via email	IO" response indicate to Dam Safety Ma	ates no is	sues (	were o	bserved	
							ACTION			
ITEM		YES N	0	DESCRIPTION			MONITOR	NVESTIGATE	SENT TO DSM	
CREST	General Condit	ion: God	od / Fair / Poor	Repairs:	Date:	3350		1271	100	
Cracking		U								
Settlement		4								
Erosion Rills		L								
Animal Burrows		L								
Misalignment		F								
Vegetation (greater than 12")		L								
UPSTREAM EMBANKMENT	General Conditi	on: Goo	d/ Fair / Poor	Repairs:	Date:	ON CO.			MARIE	
Cracking		L								
Sloughing / Bulging		v	,							
Seepage		~								
Sink Holes										
Animal Burrows		-								
Erosion Rills		-								
Slope Protection / Rip Rap		L	Sorayed my	mining weed	le: 0-10			100	22	
Vegetation (greater than 12")		1	- PANGEO IE	mining ward	S IN ROPER	ap gr	1 4	)[24	125	
OWNSTREAM EMBANKMENT		op. Goo	A / Fair / Poor	Repairs:	Date:		10.00	To the same	108018	
Cracking		1	T			ALTERNATION OF				
Sloughing / Bulging		1	-		-		$\dashv$			
Seepage		-					$\dashv$			
Sink Holes		V					-			
Sand Boils (indicate if flowing and color)		-	<del>                                     </del>				$\dashv$			
Animal Burrows		V	-					-		
Erosion Rills		V					$\dashv$			
Vegetation (greater than 12")		K	-	<u> </u>	· · · · · · · · · · · · · · · · · · ·		$\dashv$			
SPILLWAY(S)	General Condition			Repairs:	Date:	1174		1701	10011001	
Actively Flowing (provide de	AMALE DOGGE			-		1- 1		4. 1		
Obstructions Present	,	V	41	ping continue			<u>-i\$</u>	16		
Seepage			60	100 40 04	dischar	ge	-		-	
Sand Boils (indicate if flowing and color)		L	small see	-04 :-01-	2-1	-	$\dashv$		-	
Erosion Rills		U	JUNAN SEE	per inside	Discharge		-			
PERIMTER FENCING/GATES	General Condition	on: 600	Fair / Poor	Repairs:	Date:	51/4				
Evidence of damage or tan	The state of the s	V		pundi	Date.	PART I				
Evidence of unauthorized access		L					-			

Gates closed and locked