CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Edwar				LL. A	DM. Code 845 / 40	, ci k i dit 25,	Date: 1/3/	24				
Impoundment Name: Ash Po						Time: 124		_				
			W1438050005-01			Inspec		M. Davis				
						тэрсс	so.(s). <u>//</u>					
		35°		Р	recip. (last 48 hrs):	O**		Pool Elev.: 438.8				
"VEC" rosponses requi	ire description	(size denth e	ytents	colo	r) and location in "DES	CRIPTION" section.	"NO" response indic	ates no i	ssues	were o	bserve	
at the time of inspect	ion. If "ACTIOI	N" selected is '	INVES	TIGAT	E", please indicate da	te forwarded via em	ail to Dam Safety Ma	anager (D	SM).	Attach	n	
additional sheets as necessary. Circle General Cond									ACTION			
ITEM									ACTION			
			YES	NO		DESCRIPTION	ION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST		General Cond	dition:	6000	/ Fair / Poor	Repairs:	Date:					
Cracking				~								
Settlement				~								
Erosion Rills				~								
Animal Burrov	VS			~								
Misalignment				-								
Vegetation (gr	eater than 12"	')		~								
UPSTREAM EME	BANKMENT	General Con	dition:	0000	/ Fair / Poor	Repairs:	Date:					
Cracking												
Sloughing / Bu	ılging			1		<u></u>						
page				1								
Sink Holes				L						<u> </u>		
Animal Burrov	VS			1	<u> </u>							
Erosion Rills				~						<u> </u>	↓	
Slope Protection / Rip Rap				V						—	 	
Vegetation (gr				1	<u> </u>			\longrightarrow				
DOWNSTREAM EN	/BANKMENT	General Con	dition	6000	/ Fair / Poor	Repairs:	Date:					
Cracking				V							-	
Sloughing / Bu	ılging			V						 	-	
Seepage				V	1							
Sink Holes				V						 	-	
Sand Boils (ind	icate if flowing	g and color)		V	1					—	-	
Animal Burrows				V								
Erosion Rills			V	1_						↓		
Vegetation (gr	eater than 12'			1			10.2			-		
SPILLWA	Y(S)	General Con	dition	: 6000	/ Fair / Poor	Repairs:	Date:				-	
Actively Flowing (provide depth)				V	Pond level i	5 25" below	Discharge			↓		
Obstructions Present				V	Pond level i		U			 		
Seepage			-		Small bole	inside A	Scharge			 	-	
Sand Boils (inc	licate if flowin	g and color)		V						 		
Erosion Rills				K	1							
P VITER FENC	ING/GATES	General Con	dition	: Good	/ Fair / Poor	Repairs:	Date:					
Evidence of d	amage or ta	ampering		V								
Evidence of u	nauthorized	access		1	1							

Gates closed and locked