CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257 Date: 02/14/24
Time: 9:15 Am
Inspector(s): Kevin Longer **Edwards** Station: Impoundment Name: Ash Pond IEPA Number: W1438050005-01 Pool Elev.: 444.0 Sky: Clean Temp.: 36° F Precip. (last 48 hrs): 0 " "YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section. **ACTION NVESTIGATE** YES NO MONITOR **ITEM DESCRIPTION** SENT TO DSM **CREST** General Condition Good/ Fair / Poor Repairs: Date: Cracking Settlement **Erosion Rills** V **Animal Burrows** V Misalignment Vegetation (greater than 12") Repairs: Date: V Cracking V Sloughing / Bulging Seepage Sink Holes **Animal Burrows** L **Erosion Rills**

UPSTREAM EMBANKMENT | General Condition Good / Fair / Poor No Issues Slope Protection / Rip Rap Vegetation (greater than 12") DOWNSTREAM EMBANKMENT | General Condition (Good / Fair / Poor Repairs: Date: V Cracking V Sloughing / Bulging Seepage Sink Holes V Sand Boils (indicate if flowing and color) **Animal Burrows** V **Erosion Rills** Vegetation (greater than 12") SPILLWAY(S) General Condition: Good / Fair / Poor Repairs: Date: Actively Flowing (provide depth) Less thor 1 V **Obstructions Present** V Seepage Sand Boils (indicate if flowing and color) **Erosion Rills** PERIMTER FENCING/GATES | General Condition: Good / Fair / Poor Repairs: Date: Evidence of damage or tampering レ Evidence of unauthorized access Gates closed and locked