## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Edward Impoundment Name: Ash F IEPA Number: W143805				Date:	8-6-25			
			•	Time:	Dano	-		
		5-01		Inspector(s):	M. Davis			
Sky: Clear Temp.:	70°		recip. (last 48 hrs):			43	3.5	
YES" responses require description (size the time of inspection. If "ACTION" !								
dditional sheets as necessary. Circle G	General Condition	for ea	ch section.					. 1
						A	ACTION	
ITEM	YES	NO		DESCRIPTION		MONITOR	NVESTIGATE	SENT TO DSM
CREST G	eneral Condition:	Good	Fair / Poor	Repairs:	Date:			
Cracking		7						
Settlement		U						$\Box$
Erosion Rills		L						
Animal Burrows		V						
Misalignment		-						
Vegetation (greater than 12")		V	Trying to	schedule avas	s to be c	4		
UPSTREAM EMBANKMENT G	eneral Condition:	Good	/ Fair / Poor		Date:			
Cracking		-						
Sloughing / Bulging								
Seepage		L						
Sink Holes		~						
Animal Burrows				4				
Erosion Rills		V						
Slope Protection / Rip Rap		L						
Vegetation (greater than 12")		V						
OOWNSTREAM EMBANKMENT G	eneral Condition	Good	/Fair / Poor	Repairs:	Date:			
Cracking								
Sloughing / Bulging		-						
Seepage		-						
Sink Holes								
Sand Boils (indicate if flowing an	d color)	-						
Animal Burrows		V						
Erosion Rills		~						
Vegetation (greater than 12")	V		Trying to	schedule grass	coutting			
SPILLWAY(S) Ge	eneral Condition:	Good	Fair / Poor	Repairs:	Date:		TE S	
Actively Flowing (provide depth	1)	V	Pondwater	level is 60"	below Ou	1fa/	1	0
Obstructions Present		-						
Seepage								
Sand Boils (indicate if flowing an	d color)	レ			10			
Erosion Rills		V						
PERIMTER FENCING/GATES G	eneral Condition:		/ Fair / Poor	Repairs:	Date:			
Evidence of damage or tamp	ering						***	
Evidence of unauthorized ac	cess	L	/					
Gates closed and locked	V							-

N. Pord water level - 449', i

S. Pond water level - 4425'