	CC	R Im	poundment Week	y Inspection							
	35 I	LL. A	DM. Code 845 / 40	CFR Part 257							
Station: Edward			ds Date: 8-13-25								
Impoundment Name: Ash Po				Time: 0650							
IEPA Number:	W1438050005	5-01 Inspector(s): M. Davis									
Clear Temp.:	69° F	. Р	recip. (last 48 hrs):	.62"		Pool	Elev.:	43	.47		
"YES" responses require description (at the time of inspection. If "ACTION additional sheets as necessary. Circle	" selected is "INVES	TIGAT	E", please indicate date								
								ACTION			
ITEM	YES	NO		DESCRIPTION	V		MONITOR	INVESTIGATE	SENT TO DSM		
CREST	General Condition	Good	Fair / Poor	Repairs:	С	ate:					
Cracking		L									
Settlement		-									
Erosion Rills		V									
Animal Burrows		V									
Misalignment		V									
Vegetation (greater than 12")		-	Gross Cu	at on 8-	12-2	5					

Repairs:

Repairs:

Repairs:

Grass cut

General Condition: Good / Fair / Poor

V

L.idence of unauthorized access Gates closed and locked N. Pond water level - 449' S. Pond water Level - 442. Revised 09-13-2!

PERIMTER FENCING/GATES General Condition Good Fair / Poor

UPSTREAM EMBANKMENT | General Condition: Good) Fair / Poor

DOWNSTREAM EMBANKMENT | General Condition Good Fair / Poor

Cracking

Seepage Sink Holes

Erosion Rills

Cracking

Seepage Sink Holes

Seepage

Erosion Rills

Sloughing / Bulging

mal Burrows

Sloughing / Bulging

Animal Burrows Erosion Rills

Slope Protection / Rip Rap Vegetation (greater than 12")

Sand Boils (indicate if flowing and color)

Vegetation (greater than 12")

Actively Flowing (provide depth)

Sand Boils (indicate if flowing and color)

dence of damage or tampering

SPILLWAY(S)

Obstructions Present

Date:

Date:

Date:

60" below