

CCR Impoundment Weekly Inspection
35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Hennepin
Impoundment Name: West Ash Pond 1
IEPA Number: W1550100002-01

Date: 3 Dec 2025
Time: 07:17
Inspector(s): Mike O'le

Sky: Cloudy Temp.: 26°F Precip. (last 48 hrs): 4/10" liquid Pool Elev.: 440 3/4'

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM	YES	NO	DESCRIPTION	ACTION		
				MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Settlement	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Misalignment	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
UPSTREAM EMBANKMENT	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Sloughing / Bulging	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sink Holes	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Slope Protection / Rip Rap	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
DOWNTSTREAM EMBANKMENT	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Sloughing / Bulging	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sink Holes	<input checked="" type="checkbox"/>					
Sand Boils (indicate if flowing and color)	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
SPILLWAY(S)	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Actively Flowing (provide depth)	<input checked="" type="checkbox"/>					
Obstructions Present	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sand Boils (indicate if flowing and color)	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					

CCR Impoundment Weekly Inspection
35 ILL. ADM. Code 845 / 40 CFR Part 257

Station: Hennepin
Impoundment Name: East Ash Pond 2
IEPA Number: W1550100002-04

Date: 3 Dec 2025
Time: 07:17
Inspector(s): Mike Olle

Sky: Cloudy Temp.: 25°F Precip. (last 48 hrs): 4/10" liquid Pool Elev.: 440 3/4'

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM	YES	NO	DESCRIPTION	ACTION		
				MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condition: <u>Good</u> Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Settlement	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Misalignment	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
UPSTREAM EMBANKMENT	General Condition: <u>Good</u> Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Sloughing / Bulging	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sink Holes	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Slope Protection / Rip Rap	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
DOWNSTREAM EMBANKMENT	General Condition: <u>Good</u> Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Sloughing / Bulging	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sink Holes	<input checked="" type="checkbox"/>					
Sand Boils (indicate if flowing and color)	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
SPILLWAY(S)	General Condition: <u>Good</u> Fair / Poor			Repairs:	Date:	
Actively Flowing (provide depth)	<input checked="" type="checkbox"/>					
Obstructions Present	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sand Boils (indicate if flowing and color)	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					

CCR Impoundment Weekly Inspection
35 ILL. ADM. CODE 845 / 40 CFR Part 257

Station: Hennepin
 Impoundment Name: New East Primary Pond
 IEPA Number: W1550100002-05

Date: 3 Dec 2025
 Time: 07:17
 Inspector(s): Mike O'le

Sky: Cloudy Temp.: 25°F Precip. (last 48 hrs): 4/10" liquid Pool Elev.: 440 3/4'

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM	YES	NO	DESCRIPTION	ACTION		
				MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Settlement	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Misalignment	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
UPSTREAM EMBANKMENT	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Sloughing / Bulging	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sink Holes	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Slope Protection / Rip Rap	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
DOWNTSTREAM EMBANKMENT	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Sloughing / Bulging	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sink Holes	<input checked="" type="checkbox"/>					
Sand Boils (indicate if flowing and color)	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
SPILLWAY(S)	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Actively Flowing (provide depth)	<input checked="" type="checkbox"/>					
Obstructions Present	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sand Boils (indicate if flowing and color)	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					

CCR Impoundment Weekly Inspection
35 ILL. ADM. CODE 845 / 40 CFR Part 257

Station: Hennepin

Date: 3 Dec 2025

Impoundment Name: East Pond 4

Time: 07:17

IEPA Number: W1550100002-07

Inspector(s): Mike One

Sky: Cloudy

Temp.: 26°F

Precip. (last 48 hrs):

4/10" liquid

Pool Elev.: 440 3/4'

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM	YES	NO	DESCRIPTION	ACTION		
				MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Settlement	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Misalignment	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
UPSTREAM EMBANKMENT	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Sloughing / Bulging	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sink Holes	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Slope Protection / Rip Rap	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
DOWNTSTREAM EMBANKMENT	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Cracking	<input checked="" type="checkbox"/>					
Sloughing / Bulging	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sink Holes	<input checked="" type="checkbox"/>					
Sand Boils (indicate if flowing and color)	<input checked="" type="checkbox"/>					
Animal Burrows	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					
Vegetation (greater than 12")	<input checked="" type="checkbox"/>					
SPILLWAY(S)	General Condition: <u>Good</u> / Fair / Poor			Repairs:	Date:	
Actively Flowing (provide depth)	<input checked="" type="checkbox"/>					
Obstructions Present	<input checked="" type="checkbox"/>					
Seepage	<input checked="" type="checkbox"/>					
Sand Boils (indicate if flowing and color)	<input checked="" type="checkbox"/>					
Erosion Rills	<input checked="" type="checkbox"/>					