CCR Impoundment Weekly Inspection 35 ILL, ADM, Code 845 / 40 CFR Part 257

j.		ILL.	ADM. Code 845 / 40 CFR Part 257	.			
Station: <u>Jopp</u>	Date:	8421			¥		
Impoundment Name: Eggs	Z Time:	14:38		•			
IEPA Number: W1270	21000	04.	02 Inspector(s):	RFaighn		•	
01	1.0			- Stoay in	·	•	
Sky: Clear Temp.: 82	<i>[-</i>	_ !	Precip. (last 48 hrs):	Pool	Elev.:	4.1	42
\$1.							10
YES" responses require description (size, depth	, extent	s, col	or) and location in "DESCRIPTION" section. "NO" res	ponse indicates no	n issues	Were	hearvac
t the time of inspection. If "ACHON" selected	IS "INVE	STIGA	TE", please indicate date forwarded via email to Dan	n Safety Manager	(DSM)	. Attach	nservet 1
dditional sheets as necessary. Circle General C	ondition	for e	ach section.				
					ACTION		
ITEM	VES	NO	DECORIOTION		_ ا	, TE	
116141	1,13	"	DESCRIPTION		💆	16,	2
					MONITOR	NVESTIGATE	SENT TO DSM
CREST. General Co	ndition	Good	7 Fair / Poor Repairs:	Date:	≥] <u>13</u> 50
Cracking	Delica delica i sectivo	V	· · · · · · · · · · · · · · · · · · ·	vale.	WAY WE	WARE TO	神经层次
Settlement	_	1			├──		
Erosion Rills		~			 		# # L &
Animal Burrows		1			 	1	
Misalignment		V			 	 	
'egetation (greater than 12")		V			 		-
TREAM EMBANKMENT: General Co	nditlon:	Good	P Fair / Poor Repairs: 2	Date:	MEDICAL IN	Wilsta	34,0000.0
Cracking		~	· · · · · · · · · · · · · · · · · · ·		新新新港	\$400 E	
Sloughing / Bulging		V			<u> </u>		
Seepage		1				 	-
Sink Holes		V		<u> </u>			
Animal Burrows		~					
Erosion Rills		V			<u> </u>	<u> </u>	
Slope Protection / Rip Rap							
Vegetation (greater than 12")			Some tall reels at water line.			<u> </u>	1,
OWNSTREAM EMBANKMENT General Cor	idition:(Good	是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	Date:	Monachine.		WW. 18
Cracking		~			- with the seaton	160 Mile (2004)	
Sloughing / Bulging		~					
Seepage		V				<u> </u>	<u> </u>
Sink Holes		V				ļ ——	
Sand Boils (Indicate if flowing and color)		V				ļ	
Animal Burrows		V					
Erosion Rills		V			 		
Vegetation (greater than 12")	~		Grass > 12 inches				7 - 34
S SPILEWAY(S) General Con	dition:	500d	Company of the Compan	Date:	727 A	V 1225	Andrews
Áctively Flowing (provide depth)	V		4" water flow at outfall stru	Characteristic enter to the self. Deer a production where	9500 B.S.	2015年(2月17)	200000
bstructions Present		/	1700 400 0110	<u> </u>	 -	 	
ප්éepage		V					
Sand Boils (Indicate if flowing and color)					— —	 	

Erosion Rills

1. 1.1.