Sky: Cloudy Temp.: 79 of Precip. (last 48 hrs): 0.5 of CFR Part 257

Station: 70 of Precip. (last 48 hrs): 0.5 of Pool Elev.: 4.5

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

				ACTION		
ITEM	YES	NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM
CREST General Conc	lition	Good	Fair / Poor Repairs: Date:	apalis 4		
Cracking		2				
Settlement		2		·		
Erosion Rills		Z				
Animal Burrows		L				
Misalignment		1				
Vegetation (greater than 12")		1				
UPSTREAM EMBANKMENT General Conc	lition;	6000	/ Fair / Poor Repairs Date:			
Cracking		4	~			
Sloughing / Bulging		2				
Seepage		2				
Sink Holes		1	-			
Animal Burrows		2				
Erosion Rills		1				
Slope Protection / Rip Rap		1				
Vegetation (greater than 12")	1		only at Waterline - Dead Uses.			
DOWNSTREAM EMBANKMENT General Cond	itiony	good	Fair / Poor Repairs: Date:			
Cracking						
Sloughing / Bulging		ا	-			
Seepage		1				
Sink Holes		0				
Sand Boils (indicate if flowing and color)		2				
Animal Burrows		4				
Erosion Rills		6				
Vegetation (greater than 12")		1				
SPILLWAY(S) General Cond	ition:	Good	/ Fair / Poor Repairs; Date;		125.000	
Actively Flowing (provide depth)	2		a foculation at Ocital			
Obstructions Present		L	L			
Seepage		<u></u>				
Sand Boils (indicate if flowing and color)		2				
Erosion Rills		L				