CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

1	35	ILL.	ADM. Code 845 / 40 CFR Part 257				
Station: Joppe	λ		Date: 8-10-22			=	
Impoundment Name: Eggs	7sh 1	on	Time: 13:3/	Control Control			
IEPA Number: W1270	1000	24.	02 Inspector(s): R Faugh				
Sky: Cloudy Temp.: 73			124	Elev.:	4,	48'	
YES" responses require description (size, depth, the time of inspection. If "ACTION" selected is dditional sheets as necessary. Circle General Co	s "INVES	STIGA	or) and location in "DESCRIPTION" section. "NO" response indicates no TE", please indicate date forwarded via email to Dam Safety Manager each section.	issues (DSM) .	were ob Attach	bserve	
					CTION	N	
ITEM	YES	NO	DESCRIPTION	MONITOR	NVESTIGATE	SENT TO DSM	
CRÉST General Cor	ndition	Good	Fair / Poor Repairs: Date:			S	
Cracking		V		120017500	28/07/2/2023		
Settlement		V				1.5	
Erosion Rills		V				15.5	
Animal Burrows		V		2	7	7,2	
Misalignment		V					
'egetation (greater than 12")		V			-		
TREAM EMBANKMENT General Cor	idition	Good	Fair / Poor Repairs: Date:	A TOTAL		Many	
Cracking		V		-0.5-10-0.51		7-2/18/6	
Sloughing / Bulging		V				<u> </u>	
Seepage		V					
Sink Holes		V			1/2	-	
Animal Burrows		V					
Erosion Rills		1/					
Slope Protection / Rip Rap		V	1			2 - 1	
Vegetation (greater than 12")	V		Deal vegetation at water line.		·	1.1	
OWNSTREAM EMBANKMENT General Con	dition	Good	Fair / Poor Repairs: Date:		Arro		
Cracking	T	V		\$2,910.2E	0.0562150	2-90-6	
Sloughing / Bulging		V					
Seepage		V		-			
Sink Holes	T	V				-	
Sand Boils (indicate if flowing and color)	\top	v		-		 	
Animal Burrows	TT	V			- 1	-	
Erosion Rills	+	1/		-		 	
Vegetation (greater than 12")			Gasson slupe.	 	+ 1		
SPILLWAY(S) General Con	dition:	ood		1 Apply 18	Applica-	State	
Actively Flowing (provide depth)	T		4.5" water flow at weir.	33404	(B) (S)	200	
pstructions Present	++	V	www.weir.	-		ļ	

Seepage

Sand Boils (indicate if flowing and color)
Erosion Rills