CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Impoundment Name: East /		on,	Date: 10 18 12 7 7 7 15 10 18 12 7 7 15 16 16 16 16 16 16 16 16 16 16 16 16 16				
Sky: Gear Temp.: 469	<u>'</u>		Precip. (last 48 hrs): O'' Pool	Elev.:	.4	.16	
18 1						34	
"YES" responses require description (size, depth,	extent	s, cok	or) and location in "DESCRIPTION" section. "NO" response indicates no	Issues	were of	bservec	
additional sheets as necessary. Circle General Co	ndition	onga 1 for e	TE", please indicate date forwarded via email to Dam Safety Manager ((DSM).	Attach		
					ACTION		
ITEM	YES	NO	DESCRIPTION	MONITOR	NVESTIGATE	SENT TO DSM	
GREST General Cor	dition;	Goog	Repairs: Date:			S D	
Cracking		~	Taras de la casa de la	NEWSTAND CHECK	AND CASE	ARCHINE AND	
Settlement		1				3 3 4	
Erosion Rills		~				1111	
Animal Burrows		L				7.14	
Misalignment		.v					
egetation (greater than 12")		V				-	
TREAM EMBANKMENT General Con	dition	Good	Fair / Poor Repairs: Date:				
Cracking		7		uğuzdanı viles	A. SERVICE	次表现的社	
Sloughing / Bulging		\					
Seepage		V		· ·		<u> </u>	
Sink Holes 👫 🔭		レ			- i		
Animal Burrows		レ					
Erosion Rilis		~					
Slope Protection / Rip Rap		V				2 .	
Vegetation (greater than 12")	V		Deal varetation at unter line.			:,7	
DOWNSTREAM EMBANKMENT General Con-	dition (3000	/Fair/Poor Repairs: Date:			加德的	
Cracking		~		art Astronom	SAN MESSAGE	2148113	
Sloughing / Bulging		4		<u> </u>		 	
Seepage		~	1		·	<u> </u>	
Sink Holes		L		 		<u></u>	
Sand Boils (indicate if flowing and color)		V					
Animal Burrows		V		ļ		 	
Erosion Rills		V		 		7	
Vegetation (greater than 12")		V			 -		
SPILEWAY(S) General Conc	ition. A	66a),	Fair / Poor Repairs Date:		\$050 P	3.5 F	
Actively Flowing (provide depth)	Ī	L	- And Andrew Company of Land Management Company of Company Andrew Company Andrew And	\$0\$E356	19 TO 19	李明是法	
ostructions Present		V	1	 		 	
eepage		V			 		
Sand Boils (Indicate if flowing and color)		V			<u> </u>	<u> </u>	

Erosion Rills