## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| / \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\   |                     | 33 IL                  | L. ADIVI. Code    | 045 / 40 | CFR Part 257  |          |  |               |                  |
|--|---------------------|------------------------|-------------------|----------|---------------|----------|--|---------------|------------------|
| Station: Joppa   |                     |                        |                   |          | Date:         | 12-13-22 | •  |               |                  |
| Impoundment Name: East Ash Pond  |                     |                        | end               |          | Time:         | 08:00    |  | Ř             |                  |
| IEPA Nur   | nber: <u>W12701</u> | 0000                   | 4-02              |          | Inspector(s): | REalphy  |  |               |                  |
| sky: <u>Clouds</u> Te  | emp.: 41%           |                        | Precip. (last     | 48 hrs): | 0''           | Pool     | Elev.:   | 4,0           | 22               |
| "YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section. |                     |                        |                   |          |               |          |  |               |                  |
|  |                     |                        |                   |          |               |          | F  | CTIO          | N                |
| ITEM   |                     | YES                    | NO                |          | DESCRIPTION   |          | MONITOR  | NVESTIGATE    | SENT TO<br>DSM   |
| • CREST  | General Conc        | dition: <mark>(</mark> | ood / Fair / Poor |          | Repairs:      | Date:    | (400 to 100 to 1 |               |                  |
| Cracking   |                     |                        | ~                 |          |               |          |  | consolements. | - 575-256-2-15-3 |
| Settlement   |                     |                        | V                 |          |               | 10       |  | 18            | 21.3             |
| Erosion Rills  |                     |                        | V                 |          | :             |          |  |               | 1.00             |
| Animal Burrows   |                     |                        | 10                |          |               |          |  |               | 1.22             |

Misalignment egetation (greater than 12") TREAM EMBANKMENT | General Condition: Good ) Fair / Poor | Repairs: Date: Cracking Sloughing / Bulging Seepage Sink Holes Animal Burrows V **Erosion Rills** Slope Protection / Rip Rap Deal regetation at water line Vegetation (greater than 12") DOWNSTREAM EMBANKMENT General Condition: Good Fair / Poor Date: Cracking Sloughing / Bulging V Seepage Sink Holes Sand Boils (indicate if flowing and color) **Animal Burrows** V **Erosion Rills** V Vegetation (greater than 12") § SPILLWAY(S) General Condition: Good) Fair / Poor Repairs: Date: Actively Flowing (provide depth) / ostructions Present

V

Jeepage

Erosion Rills

Sand Boils (indicate if flowing and color)